

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI22013002/RWY3E2**Date:** 11/04/2023**REFERENCE**

Insured/Claimant:	QOOL ENVIRO PTE. LTD.	Policy No:	DMCG22006968
Date of Loss:	22/12/2022	Nature of Claim:	OD
		Claim No:	CDMCG22002774

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP3053Y		
Make & Model:	ISUZU FVR34SUQDC, 7.8 D (M)	Engine No:	6HK1683379
Reg. Date:	15/06/2016 (Man. Year: 2016)	Chassis No:	JALFVR347G7000718
Colour:	Orange	Odometer:	487368 km
Engine Capacity:	7790 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	ANNAITE 8 mm	Rear Left Side:	ANNAITE 8/8 mm
Front Right Side:	ANNAITE 8 mm	Rear Right Side:	ANNAITE 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,426.60	2,426.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	1,030.00	300.00	22.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,756.60	3,456.60	300.00	7.99
+ GST 7.00/8.00% (S\$)	262.96	276.53	-13.57	-5.16
Nett Amount (S\$)	4,019.56	3,733.13	286.43	7.13

INSPECTION

Date of Assignment:	30/12/2022	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	30/12/2022	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

EXCESS: \$3,500.00

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jan 2023)	
Parts:	N/A	ISUZU FVR34SUQDC 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP3053Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Bent	690.00 F	*690.00 F
2	1		*FRT BUMPER OUTER GARNISH RH (WCP)	Scratched	26.00 F	*26.00 F
3	1		*FRT HEADLAMP RH (WCP)	Cracked	335.00 F	*335.00 F
4	1		*FRT HEADLAMP BRACKET RH (WCP)	Bent	235.00 F	*235.00 F
5	1		*FRT SIGNAL LAMP RH (WCP)	Cracked	160.00 F	*160.00 F
6	1		*FRT DOOR OUTER LOWER GARNISH RH (WCP)	Cracked	145.00 F	*145.00 F
7	1		*FRT DOOR LOWER SIDE SIGNAL LAMP RH (WCP)	Scratched	40.00 F	*40.00 F
8	1		*FRT UPPER STEP GARNISH RH (WCP)	Cracked	130.00 F	*130.00 F
9	1		*FRT LOWER STEP GARNISH RH (WCP)	Missing	55.00 F	*55.00 F
10	1		*FRT LOWER STEP GARNISH SIDE HOLE COVER RH (WCP)	Missing	18.00 F	*18.00 F
11	1		*FRT LOWER STEP ALLOY RH (WCP)	Missing	155.00 F	*155.00 F
12	1		*FRT STEP PANEL BRACKET RH (WCP)	Bent	205.00 F	*205.00 F
13	1		*FRT DOOR LOWER SIGNAL LAMP BASE RH (WCP)	Cracked	12.00 F	*12.00 F

F=Franchise part.

Sub Total (S\$)	2,206.00	2,206.00
+ Margin on L,N Items 10.00/10.00% (S\$)	220.60	220.60
Total Parts (S\$)	2,426.60	2,426.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT DOOR RH,FRT CORNER PANEL, WELD,REMOVE & REPLACE ABOVE PARTS	New	700.00	500.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New	600.00	500.00
3	TO CHECK WIRING	New	30.00	30.00
Gross Labour Cost (S\$)			1,330.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >