



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 957Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LHF FENDER	DENTED	879.30	879.30
1	LH DOOR	TO REPAIR SEE LABOUR	1,741.90	-
1	LH DOOR WEATHER-STRIP	NOT NECESSARY	149.20	-
1	LH DOOR TOP HINGE	TO REPAIR SEE LABOUR	76.10	-
1	LH DOOR LOWER HINGE	TO REPAIR SEE LABOUR	76.10	-
1	LH DOOR PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-292.26	-87.93
			2,630.34	791.37
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET SIDE SKIRT (SN)	N/S DENTED / CRACKED	600.00	600.00
1	SET WING MIRROR (SN)	N/S BROKEN	450.00	450.00
			1,050.00	1,050.00
	<b><u>LABOUR</u></b>			
	TO CHECK FRONT LIGHTINGS & WIRINGS.		50.00	30.00
	TO REMOVE & TRANSFER LH DOOR FITTINGS.	NOT NECESSARY	120.00	-
	ANTI RUST.		100.00	30.00
	TO RENEW DAMAGED PARTS. REFORM, REPAIR & RE-ALIGN ALL AFFECTED AREA. INCLUSIVE OF THE REPAIR OF LH DOOR, LH DOOR TOP HINGE, LH DOOR LOWER HINGE AND LH DOOR PILLAR.		750.00	400.00
	TO RESPRAY AFFECTED PARTS.		1,000.00	700.00
			2,020.00	1,160.00
	<b>GRAND TOTAL</b>		<b>5,700.34</b>	<b>3,001.37</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,400.00</b>
---	--	--	-----------------

Report Ref No. CS3/LPC22007916/Dqy3e2-1

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**