



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 7345K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR (NO DAMAGE)	NOT NECESSARY	156.00	-
1	SET HANDLE BAR END (NO DAMAGE)	NOT NECESSARY	50.00	-
1	LEVER LH	USED BACK	35.00	-
1	LEVER RH	NOT NECESSARY	35.00	-
1	SET MIRROR	CUT	92.00	92.00
1	FRONT COVER	SERVICEABLE	109.00	-
1	FRONT STAY (CAN'T SEE DAMAGE)	NOT NECESSARY	470.00	-
1	FRONT FENDER COMPLETE	CUT	167.00	167.00
1	FRONT INNER FENDER	SERVICEABLE	62.00	-
2	FRONT BODY COWLING @142.00	CUT	284.00	284.00
2	FRONT MIDDLE PANEL ASSY @90.00	CUT	180.00	180.00
1	PAIR FRONT FLASHER LIGHT	SERVICEABLE	124.00	-
2	FLOOR BOARD @120.00	CUT	240.00	240.00
2	SETS FLOOR MAT @56.00	NECESSARY	112.00	112.00
2	FLOOR BOARD SIDE MOLE @80.00	CUT	160.00	160.00
1	UNDER COVER	CUT	90.00	90.00
2	REAR FOOTREST ASSY @68.00	O/S CUT	136.00	68.00
1	MAIN STAND COMPLETE	USED BACK	192.00	-
1	CRANKCASE OUTER COVER LH	CUT	81.00	81.00
1	AIR FILTER OUTER COVER	SERVICEABLE	59.00	-
2	REAR SIDE COVER COMPLETE @192.00	GRAZED	384.00	384.00
1	RADIATOR COVER	USED BACK	46.00	-
1	MUFFLER PROTECTOR	GRAZED	75.00	75.00
1	EXHAUST MUFFLER	USED BACK	546.00	-
	LESS 10% DISCOUNT		-388.50	-193.30
			3,496.50	1,739.70
SPECIAL NETT ITEMS				
1	ADD SPECIAL NETT FROM ABOVE (SN)	NOT NECESSARY	60.00	-
1	SET STEERING CONE & BEARING (SN)	NOT NECESSARY	100.00	-
			160.00	-

Report Ref No. CS3/LPC22010514/Uqy3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING FEE.		80.00	60.00
	REPAIR & ALIGN FRONT FORKS & STEERING COMPONENTS.	NOT NECESSARY	200.00	-
	RENEW DAMAGED PARTS & REPAIR AFFECTED AREAS.		500.00	300.00
			780.00	360.00
	GRAND TOTAL		4,436.50	2,099.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS3/LPC22010514/Uqy3m4-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.