2/3/23, 1:10 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited Our File No: CS/ICS22013015/KWY3Q2

10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Date: 03/02/2023

REFERENCE

Insured/Claimant: SZE SENG CHUAN Policy No: MPC22P00009600

Date of Loss: 24/12/2022 Nature of Claim: OD Claim No: DMPC2200660H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV4174X

Make & Model: TOYOTA VIOS E, 1.5 (A) Engine No: 1NZY001289

Reg. Date: 26/01/2010 (Man. Year: 2009) Chassis No: MR053HY9305139838

Colour: Metallic Blue Odometer: 280133 km

Engine Capacity: 1497 cc

Market Value/New Car

Price:

S\$58,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,915.00	2,915.00	0.00	0.00
Miscellaneous Items	35.00	35.00	0.00	0.00
Paintwork Materials	800.00	800.00	0.00	0.00
Labour	1,320.00	700.00	620.00	46.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,070.00	4,450.00	620.00	12.23
- Excess (S\$)	0.00	4,000.00	-4,000.00	
(S\$)	5,070.00	450.00	4,620.00	91.12
+ GST 7.00/7.00% (S\$)	354.90	31.50	323.40	91.12
Nett Amount (S\$)	5,424.90	481.50	4,943.40	91.12

INSPECTION

Date of Assignment: 30/12/2022 Present Location: Convergence Automotive Pte Ltd (HQ)

Convergence Automotive Pte Ltd (HQ)

Date Inspected: 03/01/2023 Inspected At: 39 Woodlands Close, MEGA@Woodlands #01-24

Singapore 737856

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

2/3/23, 1:10 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2023)

Parts: 143 TOYOTA VIOS E 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJV4174X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount	
1	1	*FRONT BUMPER (WCP)	Cracked	190.00 F	*190.00 F	
2	1	*FRONT GRILLE (WCP)	Missing	110.00 F	*110.00 F	
3	1	*FRONT GRILLE MOULDING	Missing	60.00 F	*60.00 F	
4	1	*SUPPORT PANEL (WCP)	Bent	300.00 F	*300.00 F	
5	1	*BONNET (WCP)	Buckled	230.00 F	*230.00 F	
6	1	*BONNET LOCK (WCP)	Distorted	70.00 F	*70.00 F	
7	1	*FRONT HEADLAMP LH (WCP)	Mtg Cracked	170.00 F	*170.00 F	
8	1	*FRONT HEADLAMP RH (WCP)	Mtg Broken	170.00 F	*170.00 F	
9	1	*RADIATOR (WCP)	Punctured	550.00 F	*550.00 F	
10	1	*CONDENSER (WCP)	Punctured	550.00 F	*550.00 F	
11	1	*FRONT BUMPER RETAINER LH (WCP)	Distorted	50.00 F	*50.00 F	
12	1	*FRONT BUMPER RETAINER RH (WCP)	Distorted	50.00 F	*50.00 F	
13	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	150.00 F	*150.00 F	
F=Fra	anchise part.		_			
			Sub Total (S\$)	2,650.00	2,650.00	
		+ Margin on L,N Items 10.00/10.00% (S\$) 265.00 265.00				
			Total Parts (S\$)	2,915.00	2,915.00	
		Report was unsubmitted du	ring this print-out.			

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mat	<u>erials</u>				
1	1	SPRAY PAINT ON AFFECTED AREAS 4 PANELS		800.00	800.00
Mis	cellan	eous Items			
2	1	CARPLATE & CARPLATE HOLDER (BENT)		35.00	35.00
			Sub Total (S\$)	835.00	835.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
<u>Lab</u>	our Items					
1	NO. OF DAYS REPAIR 6 DAYS	New	1,320.00	700.00		
		Gross Labour Cost (S\$)	1,320.00	700.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >