

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 9008H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED / DENTED	1,598.00	440.10
1	FRONT BUMPER SIDE GARNISH RH	DISTORTED	159.00	159.00
1	FRONT BUMPER LOWER	SERVICEABLE	879.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	698.00	-
1	FRONT FENDER WHEEL ARCH RH	BUCKLED	387.00	136.20
1	FRONT KNUCKLE ARM RH	SERVICEABLE	612.00	-
1	FRONT KNUCKLE BEARING	NOT NECESSARY	198.00	-
1	HEADLAMP RH	SERVICEABLE	1,710.70	-
1	HEADLAMP LOWER BRACKET RH	SERVICEABLE	147.20	-
	LESS 20% DISCOUNT		-1,277.78	-147.06
			5,111.12	588.24
	SPECIAL NETT ITEMS			
10	FRONT BUMPER CLIP @\$6.50 (SN)	NECESSARY	65.00	65.00
1	FRONT BUMPER SIDE CHORME RH (SN)	SERVICEABLE	150.00	-
3	FRONT BUMPER SIDE GARNISH CLIP @\$6.50 (SN)	NECESSARY	19.50	19.50
1	FRONT BUMPER SENSOR (SN)	SERVICEABLE	220.00	-
1	FRONT SPORTS RIM RH (SN)	SERVICEABLE	1,000.00	-
			1,454.50	84.50
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		500.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		500.00	400.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	WIRING CHECK.		50.00	15.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
			1,780.00	715.00
	GRAND TOTAL		8,345.62	1,387.74

Report Ref No. CS/SMR22013022/Kvy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,100.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMR22013022/Kvy3e2

KONG SENG CHEONG

Licensed Appraiser