

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22013043/AVP3Q2**Date:** 28/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00258802200

Claimant Vehicle No : SNE679A **Insured Vehicle No :** SLH4335Z

Date of Loss: 29/12/2022 Nature of Claim: TP Claim No: SNM22D209384/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNE679A**

Make & Model: HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A) Engine No: G4FMMU073095

Reg. Date: 18/02/2022 (Man. Year: 2021) Chassis No: KMHNLN41ETNU234524

Colour: Black Odometer: 82369 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,951.92	11,016.64	6,935.28	38.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,790.00	2,750.00	3,040.00	52.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,741.92	13,766.64	9,975.28	42.02
Approved Total (Overridden) (S\$)		11,000.00		
Nett Amount (S\$)	23,741.92	11,000.00	12,741.92	53.67

INSPECTION

Date of Assignment: 30/12/2022

Date Inspected: 30/12/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2023)**Parts:** 143 HYUNDAI CN7 AVANTE 1.6 DOHC CVT S (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SNE679A)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	520.80 FL	*520.80 FL
2	1		*REAR BUMPER CENTER LAMP	Cracked	281.40 FL	*281.40 FL
3	1		*REAR BUMPER LAMP WIRE HARNESS	Not Necessary	121.00 FL	*- FL
4	2		*REAR BUMPER NUMBER PLATE LAMP	Damaged	116.00 FL	*116.00 FL
5	1		*REAR BUMPER LOWER (BLACK)	Distorted	380.60 FL	*380.60 FL
6	2		*REAR BUMPER SIDE RETAINER	Necessary	97.80 FL	*97.80 FL
7	1		*REAR BUMPER REINFORCEMENT	Distorted	394.80 FL	*394.80 FL
8	4		*REAR BUMPER BRACKET	Damaged (2 PCS ONLY)	192.00 FL	*96.00 FL
9	2		*REAR BUMPER REFLECTOR	Cracked	96.00 FL	*96.00 FL
10	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	996.80 FL	*498.40 FL
11	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	192.00 FL	*100.00 FL
12	2		*REAR BUMPER MUDFLAP	Not Necessary	284.60 FL	*- FL
13	1		*REAR BUMPER SIDE INNER LOWER GARNISH RH	Not Necessary	98.60 FL	*- FL
14	1		*REAR BUMPER SIDE INNER LOWER GARNISH LH	Not Necessary	138.60 FL	*- FL
15	2		*REAR FENDER INNER COWLING (REAR)	Not Necessary	120.00 FL	*- FL
16	2		*REAR FENDER INNER TRIM	Torn	656.00 FL	*656.00 FL
17	2		*TAILLAMP	Cracked	1,912.00 FL	*1,912.00 FL
18	2		*TAILLAMP PANEL	Buckled	509.20 FL	*509.20 FL
19	1		*BOOTLID	Distorted	2,127.60 FL	*1,782.00 FL
20	1		*BOOTLID LAMP	Cracked	1,185.80 FL	*1,185.80 FL
21	1		*BOOTLID OUTER GARNISH (OUTER)	Cracked	745.60 FL	*745.60 FL
22	1		*BOOTLID OUTER GARNISH (INNER)	Not Necessary	485.60 FL	*- FL
23	1		*BOOTLID LOGO	Necessary	84.20 FL	*84.20 FL
24	1		*BOOTLID EMBLEM S	Necessary	63.90 FL	*63.90 FL
25	1		*BOOTLID EMBLEM AVANTE	Necessary	51.20 FL	*51.20 FL
26	1		*BOOTLID DETECTOR (OUTER)	Not Necessary	265.70 FL	*- FL
27	1		*BOOTLID DETECTOR (INNER)	Cracked	285.60 FL	*185.00 FL
28	2		*BOOTLID HINGE	Not Necessary	188.60 FL	*- FL
29	2		*BOOTLID STOPPER	Not Necessary	14.00 FL	*- FL
30	1		*BOOTLID TOP LOCK	Damaged	185.70 FL	*185.70 FL
31	1		*BOOTLID LOWER LOCK	Not Necessary	38.50 FL	*- FL
32	1		*BOOTLID WEATHERSTRIP	Cut	148.20 FL	*148.20 FL
33	1		*BOOTLID INSULATOR	Deformed	385.30 FL	*285.00 FL
34	1		*BOOTLID REVERSE CAMERA	Not Necessary	826.10 FL	*- FL
35	1		*REAR END PANEL	Distorted	487.60 FL	*487.60 FL
36	1		*REAR END PANEL TOP GARNISH	Deformed	185.90 FL	*185.90 FL
37	1		*REAR STORGE BOX	Cracked	235.30 FL	*235.30 FL
38	1		*REAR FLOOR PANEL	Repair	765.50 FL	*- FL
39	1		*REAR FLOOR PANEL TOP BOARD	Deformed	425.60 FL	*361.00 FL
40	1		*REAR BLIND SPOT	N/S Cracked	2,592.80 FL	*1,296.40 FL
41	2		*REAR BLIND SPOT BRACKET	Not Necessary	338.60 FL	*- FL
42	1		*REAR BLIND SPOT WIRE HARNESS	Cut	658.00 FL	*454.00 FL
43	1		*REAR CHASSIS MEMBER LH	Repair	865.80 FL	*- FL
44	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	445.00 FL	*- FL
45	1		*REAR NUMBER PLATE (SPCIEAL TYPE)	Bent	180.00 FS	*60.00 FS
46	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET BOOT LID OUTER GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
48	1		*SET BOOT LID INSULATOR CLIP	Necessary	80.00 FS	*20.00 FS
49	1		*SET TAIL LAMP CLIP	Necessary	40.00 FS	*20.00 FS
50	1		*TAIL LAMP PANEL SEALANT	Not Necessary	40.00 FS	*- FS
51	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
52	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*60.00 FS
53	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
54	1		*REAR END PANEL INSULATION SEALANT	Necessary	150.00 FS	*60.00 FS
55	1		*REAR FLOOR PANEL INSULATION SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,189.90	13,695.80
- List Item Discount on L Items 20.00/20.00% (S\$)	4,237.98	2,679.16
Total Parts (S\$)	17,951.92	11,016.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,000.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER BOOTLID MECHANISM	New	80.00	80.00
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
9	REMOVE AND REFIX FUEL TANK	New	120.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
11	REMOVE AND REFIX REAR BLIND SPOT SENSOR AND RECODING AND CALIBRATION	New	800.00	380.00
12	REMOVE AND REFIX REVERSE CAMERA	New	80.00	50.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	250.00	0.00
			Gross Labour Cost (S\$)	5,790.00
				2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >