

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS23000007/RWY3M4**Date:** 19/01/2023**REFERENCE**

Insured/Claimant: NG WEI XIAN (HUANG WEIXIAN)
Date of Loss: 20/12/2022

Policy No: -
Nature of Claim: OD Claim No: 202222009053

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN6704K**
Make & Model: SKODA OCTAVIA, 1.4 AMBITION PLUS TSI (A) Engine No: CZDA21507
Reg. Date: 23/08/2019 (Man. Year: 2019) Chassis No: TMBBC7NE1K0171758
Colour: Black Odometer: 86091 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$94,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,287.57	4,709.22	2,578.35	35.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,020.00	2,740.00	2,280.00	45.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,307.57	7,449.22	4,858.35	39.47
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	11,707.57	6,849.22	4,858.35	41.50
+ GST 7.00/7.00% (\$\$)	819.53	479.45	340.08	41.50
Nett Amount (\$\$)	12,527.10	7,328.67	5,198.43	41.50

INSPECTION

Date of Assignment: 03/01/2023

Date Inspected: 29/12/2022 Inspected At:

VOLKSWAGEN GROUP SINGAPORE PTE LTD
247 ALEXANDRA ROAD
SINGAPORE 159934

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2023)
Parts:	143	SKODA OCTAVIA 1.4 AMBITION PLUS TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN6704K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Bent	1,303.82 FS	*1,303.82 FS
2	1		*CLIP (10PCS)	Necessary	4.25 FS	*4.25 FS
3	1		*HOOD LATCH BONNET LATCH	Not Necessary	67.90 FS	*- FS
4	1		*HOOD LATCH BONNET LOCK	Not Necessary	83.21 FS	*- FS
5	1		*SKODA EMBL	Necessary	50.56 FS	*50.56 FS
6	1		*COVER FOR FRT BUMPER	Scratched	997.29 FS	*997.29 FS
7	1		*SENSOR BRACKET	Necessary	9.73 FS	*9.73 FS
8	1		*SENSOR BRACKET	Necessary	9.73 FS	*9.73 FS
9	1		*SENSOR BRACKET	Necessary	9.73 FS	*9.73 FS
10	1		*SENSOR BRACKET	Necessary	9.73 FS	*9.73 FS
11	1		*2K-PLASTIC ADHESIVE	Necessary	61.88 FS	*61.88 FS
12	1		*BONDING AGENT FOR PLASTIC	Necessary	49.57 FS	*49.57 FS
13	1		*END PLATE BUMPER LOWER ELEMENT	Not Necessary	118.58 FS	*- FS
14	1		*UNBEKANNT RADIATOR GRILLE	Cracked	187.00 FS	*187.00 FS
15	1		*COVER STRI RADIATOR GRILLE CHROME	Cracked	200.43 FS	*200.43 FS
16	1		*STICKER OVERFILLED ENGINE	Necessary	11.83 FS	*11.83 FS
17	1		*STICKER OIL COMPLY WITH	Necessary	19.09 FS	*19.09 FS
18	1		*STICKER AC REFRIGERAN	Necessary	13.59 FS	*13.59 FS
19	1		*SUPPORT PA RADIATOR GRILLE INNER BRACKET LH	Cracked	40.77 FS	*40.77 FS
20	1		*SUPPORT PA RADIATOR GRILLE INNER BRACKET RH	Not Necessary	40.77 FS	*- FS
21	1		*COOLING AI BUMPER CTR LOWER GRILLE	Not Necessary	87.95 FS	*- FS
22	1		*COVER FOR BUMPER LOWER GRILLE LH	Scratched	30.26 FS	*30.26 FS
23	1		*COVER FOR BUMPER LOWER GRILLE RH	Not Necessary	30.26 FS	*- FS
24	1		*UNBEKANNT LHS H/LAMP	Cracked	1,576.14 FS	*1,576.14 FS
25	1		*UNBEKANNT RHS H/LAMP	Not Necessary	1,576.14 FS	*- FS
26	1		*REINFORCEM	Not Necessary	573.54 FS	*- FS
27	1		*BUFFER REINFORCEMENT FOAM	Cracked	43.82 FS	*43.82 FS
28	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	7,287.57 4,709.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	TO ALIGN LED HEADLIGHT	New	100.00	0.00
4	LABOUR	New	2,240.00	1,120.00
5	SPRAY PAINT	New	2,120.00	1,060.00
Gross Labour Cost (S\$)			5,020.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >