

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III23000018/UYA3Q2
Date: 19/05/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_03
Claimant Vehicle No :	GBJ4182E	Insured Vehicle No :	GBK8502J
Date of Loss:	30/12/2022	Nature of Claim:	TP
		Claim No:	MFL2023D0000007

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ4182E	Engine No:	K9KE628D656894
Make & Model:	NISSAN NV200, 1.5 MT (M)	Chassis No:	VSKYBAM20Z0176606
Reg. Date:	10/04/2019 (Man. Year: 2018)	Odometer:	75790 km
Colour:	Grey		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	TRANSITO 6 mm	Rear Left Side:	APLUS 6 mm
Front Right Side:	TRANSITO 6 mm	Rear Right Side:	APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,162.00	4,776.25	11,385.75	70.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,430.00	2,230.00	3,200.00	58.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,592.00	7,006.25	14,585.75	67.55
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	21,592.00	5,600.00	15,992.00	74.06
+ Car Rental (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		6,266.75		

INSPECTION

Date of Assignment:	03/01/2023	Choo Motor Spray Painter (HQ)
Date Inspected:	03/01/2023 Inspected At:	1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 08 Mar 2023)	
Parts:	N/A	NISSAN NV200 1.5 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ4182E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,455.30 F	*- FN
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	110.10 F	*- FN
3	1		*REAR BACK DOOR O/S	Badly Dented	1,645.10 F	*1,102.20 FN
4	1		*REAR BACK DOOR HINGES	Lower Bent	210.00 F	*105.00 FN
5	1		*REAR BACK DOOR RUBBER O/S	Twisted	118.00 F	*118.00 FN
6	1		*REAR BACK DOOR LOWER LOCK O/S	Damaged	399.20 F	*145.80 FN
7	1		*REAR BUMPER	Distorted	745.60 F	*632.70 FN
8	1		*REAR BUMPER SPONGE	Torn	244.50 F	*194.70 FN
9	1		*REAR BUMPER SIDE HOLDERS	O/S Cracked	130.00 F	*42.90 FN
10	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FN
11	1		*REAR END PANEL OUTER	Repair	899.20 F	*- FN
12	1		*REAR END PANEL INNER	Repair	845.90 F	*- FN
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	285.00 F	*- FN
14	1		*TAILLAMPS	O/S Cracked	1,310.00 F	*309.80 FN
15	1		*TAILLAMP HOUSING PANELS	O/S Bent / Dented	1,370.00 F	*408.10 FN
16	1		*REAR EXHAUST	Not Necessary	682.30 F	*- FN
17	1		*REAR EXHAUST MOUNTING	Not Necessary	50.00 F	*- FN
18	1		*REAR SPARE TYRE BRACKET	Not Necessary	369.20 F	*- FN
19	1		*REAR FENDERS	O/S Buckled	2,998.60 F	*1,499.30 FN
20	1		*REAR FENDER OUTER RAILING END O/S	Twisted	65.00 F	*65.00 FN
21	1		*TAILGATE 6 PAX STICKER	Necessary	20.00 FS	*10.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
23	1		*REAR WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
24	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS
25	1		*SET REAR REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
26	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
27	1		*SET REAR VIDEO CAM ASSY	Not Necessary	650.00 FS	*- FS
28	1		*SET REAR CORPORATE STICKER	Necessary	900.00 FS	*500.00 FS
29	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	16,162.00	5,242.50
- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00	466.25
Total Parts (\$)	16,162.00	4,776.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACED REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX GARNISH UPHOLSTERY	New	120.00	0.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
8	TO SPRAY RUST PROOFING	New	150.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,500.00	1,000.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	900.00
Gross Labour Cost (S\$)			5,430.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >