



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6296G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	503.04	503.04
1	REAR BUMER LOWER COVER	DEFORMED	654.96	654.96
1	REAR BUMPER LOWER RH COVER	TO REPAIR SEE LABOUR	232.00	-
1	REAR CENTRE LOWER COVER	NOT NECESSARY	148.40	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-390.10	-295.00
			1,170.30	885.00
	<b><u>NETT ITEMS</u></b>			
1	BUMPER REVERSE SENSOR (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-13.57	-
			122.13	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER ADVERTISEMENT (SN)	CUT	50.00	50.00
			50.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER RH COVER.		525.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			885.00	630.00
	<b>GRAND TOTAL</b>		<b>2,227.43</b>	<b>1,565.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,200.00</b>

Report Ref No. NS/INC23000027/Tqp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.