

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23000035/TVY3E2**Date:** 07/06/2023REFERENCE

Insured/Claimant:	JISMI BIN MOHAMMAD	Policy No:	SP2001690369-01
Date of Loss:	26/12/2022	Nature of Claim:	OD
		Claim No:	202222009145

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM6700B	Engine No:	4B12SX8885
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)	Chassis No:	JMYXTGF3WHJ000925
Reg. Date:	25/05/2017 (Man. Year: 2017)	Odometer:	73510 km
Colour:	Grey		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	BF-Goodrich 6 mm	Rear Left Side:	BF-Goodrich 6 mm
Front Right Side:	BF-Goodrich 6 mm	Rear Right Side:	BF-Goodrich 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,154.60	3,268.10	1,886.50	36.60
Miscellaneous Items	85.00	65.00	20.00	23.53
Labour	1,000.00	600.00	400.00	40.00
Paintwork Labour	1,000.00	600.00	400.00	40.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,239.60	4,533.10	2,706.50	37.38
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	7,239.60	3,933.10	3,306.50	45.67
+ GST 7.00/8.00% (S\$)	506.77	314.65	192.12	37.91
Nett Amount (S\$)	7,746.37	4,247.75	3,498.62	45.16

INSPECTION

Date of Assignment:	30/12/2022		
Date Inspected:	30/01/2023	Inspected At:	6 Marsiling Lane Singapore 739145 Repairer: Asure Auto Pte Ltd
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts: M1-SUV	MITSUBISHI OUTLANDER 2.4 CVT 4WD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6700B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	660.00 F	*660.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Not Necessary	20.00 F	*- F
3	1		*HEAD LAMP LH (WCP)	Cracked	660.00 F	*660.00 F
4	1		*FOG LAMP COVER LH (WCP)	Not Necessary	55.00 F	*- F
5	1		*FRONT FENDER LH (WCP)	Repair	460.00 F	*- F
6	1		*FOG LAMP CHROME MOULDING LH (WCP)	Cut	80.00 F	*80.00 F
7	1		*FRONT BUMPER CHROME MOULDING LH (WCP)	Cracked	145.00 F	*145.00 F
8	1		*FRONT BUMPER CENTER COVER (WCP)	Cracked	240.00 F	*240.00 F
9	1		*RADIATOR TOP COVER (WCP)	Not Necessary	50.00 F	*- F
10	1		*FRONT GRILLE (WCP)	Cracked	400.00 F	*400.00 F
11	1		*FRONT BONNET (WCP)	Repair	720.00 F	*- F
12	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	410.00 F	*- F
Supplementary #1						
13	1		*FR BPR BEAM UPP REINF (WCP)	Bent	96.00 F	*96.00 F
14	1		*HEADLAMP RH (WCP)	Cracked	690.00 F	*690.00 F

F=Franchise part.

Sub Total (S\$)	4,686.00	2,971.00
+ Margin on L,N Items 10.00/10.00% (S\$)	468.60	297.10
Total Parts (S\$)	5,154.60	3,268.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	30.00
2	1	FRONT NUMBER PLATE WITH HOLDER (CRACKED)	35.00	35.00
Sub Total (\$)			85.00	65.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	LABOUR FOR SPRAY PAINTING	New	1,000.00	600.00
Labour Items				
2	LABOUR FOR PANEL BEATING	New	1,000.00	600.00
Gross Labour Cost (\$)			2,000.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >