

SUB TO

REC BY: T. J. J. M.

REF: CS 6/1152300005/Tvj3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / VS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no/s _____
 of _____
 Insured: _____
 Policy No. SP2001690369-01
 Claims No. 202222009145
 Sum Insured: _____ Excess: 4600
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

CS	
N/S	O/S

Sal. or Market Value: 474K
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Turn Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMM67006 Yr Regn: 20/7/1 May
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
 Make: Mitsubishi Outlander cc 2360
 Colour: Grey A/C: Insured / Std / Nil / NA
 Sp. Reading: 73510 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: 3M9XT9F3WH 8000975
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55R18
 R:
 BS / DUN / EXNOVA / GY AFS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or BFGoodrich
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 26/12/2022 D.O.I. _____
 Survey held at Auto Insure
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
31/5/23	Final fig \$4533.10 confirmed by email (Red 2706.50, 37%)

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 2) 1/6/23-typist

Add Fee: : Site Insp (\$)
 : Interview (\$)

Survey Fee:	
Transportation:	
S + RS. SI	

Auto Insure Pte Ltd (HQ) (Co.Reg.No:201437380M)6 Marsiling Lane
Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims@autoinsure.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001690369-01	Date of Loss:	26/12/2022
Vehicle Reg. No.:	SMM6700B	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JISMI BIN MOHAMMAD		
Driver:	JISMI BIN MOHAMMAD		

Make/Model:	MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)	Vehicle Reg. Date:	25/05/2017
Vehicle Colour:	BROWN		
Engine No:	4B12SX8885	Chassis No:	JMYXTGF3WHJ000925
Odometer:	73510 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Present Location: **AUTO INSURE PTE LTD (HQ) (WOODLANDS)****COST OF CLAIMS**

	Amount
Parts	4,290.00
Miscellaneous Items	85.00
Labour	1,000.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (S\$)	6,375.00
+ GST 7.00% (S\$)	446.25
Nett Amount (S\$)	6,821.25

This claim is handled by: LOH CHEN KHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Dec 2022)

Parts: M1-SUV MITSUBISHI OUTLANDER 2.4 CVT 4WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	de ✓ *660.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	de ✓ *20.00 F
3	1		*HEAD LAMP LH	0.00	0.00	? *660.00 F
4	1		*FOG LAMP COVER LH	0.00	0.00	mis ✓ *55.00 F
5	1		*FRONT FENDER LH	0.00	0.00	Ry ✓ *460.00 F
6	1		*FOG LAMP CHROME MOULDING LH	0.00	0.00	? *80.00 F
7	1		*FRONT BUMPER CHROME MOULDING LH	0.00	0.00	ma ✓ *145.00 F
8	1		*FRONT BUMPER CENTER COVER	0.00	0.00	ma ✓ *240.00 F
9	1		*RADIATOR TOP COVER	0.00	0.00	? *50.00 F
10	1		*FRONT GRILLE	0.00	0.00	? *400.00 F
11	1		*FRONT BONNET	0.00	0.00	Ry ✓ *720.00 F
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *410.00 F

F=Franchise part.

Sub Total (S\$)	3,900.00
+ Margin on L,N Items 10.00% (S\$)	390.00
Total Parts (S\$)	4,290.00

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIPS	50.00 <i>zone</i>
2	1	FRONT NUMBER PLATE WITH HOLDER	35.00 <i>con</i>
Sub Total (\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	LABOUR FOR SPRAY PAINTING	New	1,000.00 <i>600</i>
Labour Items			
2	LABOUR FOR PANEL BEATING	New	1,000.00 <i>600</i>
Gross Labour Cost (\$)			2,000.00

Auto Insure Pte Ltd (HQ)/SMM6700B/30/12/2022 15:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjim 97495749
3/2/23
Not Antwise
Ex \$600
tanjim@lhauto.com
4-5 days.

p/p Reming before paint
No 2nd hand parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: