

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000037/AQP3Q2**Date:** 03/03/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00006332200
Claimant Vehicle No :	SJU1776J	Insured Vehicle No :	SJT5478Z
Date of Loss:	30/12/2022	Nature of Claim: TP	Claim No: SNM22D209394/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU1776J		
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FC9H322796
Reg. Date:	23/11/2009 (Man. Year: 2009)	Chassis No:	KNAFW611LA5156140
Colour:	White	Odometer:	221383 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,556.90	3,648.80	4,908.10	57.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,160.00	2,630.00	69.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,346.90	4,808.80	7,538.10	61.05
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	12,346.90	3,800.00	8,546.90	69.22

INSPECTION

Date of Assignment:	03/01/2023	
Date Inspected:	30/12/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2023)
Parts:	143	KIA CERATO FORTE 1.6 SX AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU1776J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	896.00 FL	*896.00 FL
2	2		*BOOT LID LAMP	Not Necessary	574.00 FL	*- FL
3	1		*BOOT LID EMBLEM KOUP	Necessary	42.00 FL	*42.00 FL
4	1		*BOOT LID WEATHERSTRIP	Cut	147.00 FL	*147.00 FL
5	1		*BOOT LID LOCK	Not Necessary	165.00 FL	*- FL
6	1		*BOOT LID CATCH	Not Necessary	45.00 FL	*- FL
7	1		*TAIL LAMP	N/S Cracked	796.00 FL	*398.00 FL
8	1		*REAR BUMPER	Deformed	689.00 FL	*689.00 FL
9	1		*REAR BUMPER LOWER LIP	Cut	395.00 FL	*395.00 FL
10	1		*REAR BUMPER REFLECTOR	N/S Cut	134.00 FL	*67.00 FL
11	5		*REAR BUMPER BRACKET	Damaged (2 PCS ONLY)	160.00 FL	*64.00 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	108.00 FL	*54.00 FL
13	1		*REAR BUMPER REINFORCEMENT C/W BRACKET	Damaged	748.00 FL	*358.00 FL
14	1		*REAR BUMPER SPONGE	Cracked	249.00 FL	*187.00 FL
15	2		*REAR FENDER INNER COWLING	Not Necessary	190.00 FL	*- FL
16	2		*REAR FENDER INNER TRIM	Not Necessary	578.00 FL	*- FL
17	1		*REAR END PANEL	Dented	387.00 FL	*387.00 FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	142.00 FL	*- FL
19	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	496.00 FL	*248.00 FL
20	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*SET REAR BUMPER SIDE SPOILER	Not Necessary	1,800.00 FS	*- FS
22	1		*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
23	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
24	1		*SET BOOT LID MOULDING CLIP	Not Necessary	30.00 FS	*- FS
25	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS
26	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
27	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
28	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
29	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
Sub Total (\$)						9,251.00 4,042.00
- List Item Discount on L Items 10.00/10.00% (\$)						694.10 393.20
Total Parts (\$)						8,556.90 3,648.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,WELDING ,GRAZING CUT ,JOIN,STRAIGHTEN ALL AFFECTED PARTS	New	1,400.00	600.00
2	TO PUTTY ,POLISH ,SPRAY PAINT ,WAX ALL AFFECTED PANELS	New	1,400.00	400.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	180.00	40.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANFER BOOTLID MECHANISM	New	80.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			3,790.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >