

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000039/TNP3Q2
Date: 25/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00261492201		
Claimant Vehicle No :	GBE8092G	Insured Vehicle No :	SMS8430K		
Date of Loss:	29/12/2022	Nature of Claim:	TP	Claim No:	SNM22D209390/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE8092G		Engine No:	1KD2568364
Make & Model:	TOYOTA HIACE, 3.0 D DX (M)		Chassis No:	KDH2010183103
Reg. Date:	30/03/2016 (Man. Year: 2015)		Odometer:	249999 km
Colour:	Silver		Engine Capacity:	2982 cc
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,772.51	2,282.47	3,490.04	60.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,090.00	1,410.00	56.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,272.51	3,372.47	4,900.04	59.23
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	8,272.51	2,700.00	5,572.51	67.36

INSPECTION

Date of Assignment:	03/01/2023	Ms Car Auto Pte Ltd (HQ)
Date Inspected:	10/01/2023 Inspected At:	8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Estimated Period of Repair:	4.0 days	Singapore 415875

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts: 213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBE8092G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	926.00 FL	*681.20 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	135.90 FL	*- FL
3	1		*FRONT DOOR LH	Bent	1,716.25 FL	*1,417.50 FL
4	1		*DOOR CENTRE PILLAR LH	Repair	759.20 FL	*- FL
5	1		*FRONT SINGER LH	Repair	153.60 FL	*- FL
6	1		*FRONT STEP PANEL LH	Cut	169.70 FL	*169.70 FL
7	1		*FRONT PANEL LH	Bent	312.80 FL	*245.00 FL
8	1		*FRONT LOWER ARM LH	Not Necessary	372.20 FL	*- FL
9	1		*FRONT KNUCKLE ARM LH	Not Necessary	451.20 FL	*- FL
10	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	264.70 FL	*- FL
11	1		*FRONT UPPER ARM BEARING LH	Not Necessary	312.60 FL	*- FL
12	1		*FRONT SHOCK ABSORBER LH	Not Necessary	296.70 FL	*- FL
13	1		*CONTROL ARM LH	Not Necessary	242.60 FL	*- FL
14	1		*FRT HEADLAMP LH	Cut	376.30 FL	*376.30 FL
15	1		*FRT HEADLAMP BRACKET LH	Distorted	113.60 FL	*113.60 FL
16	1		*FRONT DOOR COMPANY STICKER LH	Cut	100.00 FS	*30.00 FS
17	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1		*FRONT STEEL RIM LH	Not Necessary	250.00 FS	*- FS
19	1		*FRONT TYRE LH	Not Necessary	190.00 FS	*- FS
20	1		*FRONT RIM COVER LH	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,423.35	3,033.30
- List Item Discount on L Items 25.00/25.00% (S\$)	1,650.84	750.83
Total Parts (S\$)	5,772.51	2,282.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,000.00	500.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	500.00
3	R&R LH FRONT UNDERCARRIAGE	New	280.00	0.00
4	R&R LH FRONT TYRE & BALANCING	New	60.00	0.00
5	R&R LH FRONT DOOR COMPONENT	New	80.00	60.00
6	WIRING CHECK	New	80.00	30.00
Gross Labour Cost (S\$)			2,500.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >