

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123000043/KVY3M4**Date:** 12/01/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMA4609J **Insured Vehicle No :** XE5014S

Date of Loss: 03/01/2023 Nature of Claim: TP Claim No: CDMFG23000003

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA4609J**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UGR9869

Reg. Date: 08/06/2018 (Man. Year: 2018) Chassis No: MMBSTA13AJH001772

Colour: Metallic Silver Odometer: 54503 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,487.23	4,350.80	5,136.43	54.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	2,290.00	1,740.00	43.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,517.23	6,640.80	6,876.43	50.87
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	13,517.23	5,300.00	8,217.23	60.79

INSPECTION

Date of Assignment: 03/01/2023

Date Inspected: 04/01/2023 Inspected At: SQM PTE LTD (HQ)
160 SIN MING DRIVE, #06-01 SIN MING
AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jan 2023)	
Parts:	N/A	mitsubishi attrage 1.2 cvt (a) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA4609J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP RH	Serviceable	480.00 FL	*- FL
2	1		*REAR BUMPER	Mtg Cracked	628.00 FL	*628.00 FL
3	1		*REAR BUMPER RETAINER RH	Distorted	180.00 FL	*62.00 FL
4	1		*REAR FENDER RH	Bent	875.00 FL	*875.00 FL
5	1		*REAR FENDER UNDERSHIELD RH	Distorted	280.00 FL	*78.00 FL
6	2		*REAR W/SCREEN MOULDING	Necessary	228.00 FL	*136.00 FL
7	1		*REAR DOOR RH	Bent/Dented	980.00 FL	*839.00 FL
8	1		*REAR DOOR LOCK RH	Repair	323.20 FL	*- FL
9	1		*REAR DOOR PILLAR RH (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR WHEELHUB AND BEARING RH	Bent/Necessary	484.50 FL	*314.00 FL
11	1		*REAR SHOCK ABOSRBER RH	Serviceable	396.00 FL	*- FL
12	1		*REAR BUMPER LOWER SPOILER	Cracked	1,800.00 FS	*700.00 FS
13	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
14	2		*TUBE REAR W/SCREEN SEALANT	Necessary	46.00 FS	*40.00 FS
15	10		*REAR FENDER UNDERSHIELD CLIPS	Necessary	47.00 FS	*47.00 FS
16	1		*SET RH ROCKER PANEL SIDE SKIRTING	Dented/Cracked	2,200.00 FS	*800.00 FS
17	1		*REAR RH RIM (LOCAL PURCHASE)	Dented	600.00 FS	*80.00 FS
18	1		*REAR RH TYRE	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,972.70	4,644.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	485.47	293.20
Total Parts (\$\$)	9,487.23	4,350.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO DO CUTTING WELDING, REPAIR, ALIGN REPLACE ACCIDENT AFFECTED AREA	New	1,400.00	800.00
2	TRANSFER DOOR PARTS TO ANOTHER DOOR	New	120.00	60.00
3	TO REMOVE REFIX REAR W/SCREEN	New	140.00	120.00
4	TO CHECK WIRING SYSTEM, REMOVE REFIX SENSOR, CHECK DOOR, LAMP WIRING	New	150.00	60.00
5	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA INNER AND OUTER	New	1,200.00	900.00
6	LABOUR TO REPLACE BODY KIT, TO DO SEAL FOR BODYKIT	New	150.00	60.00
7	TO DO SEALANT SEAL GAP, WATERPROOFING ON REAR CUTTING WELDING AREA	New	200.00	30.00
8	TO DO ANTI RUST	New	90.00	60.00
9	TO REMOVE REFIX REPLACE GARNISH, SIDE TRIMS, UPHOLSTERY, CAR SEAR ETC	New	300.00	100.00
10	TO REPLACE REAR RIGHT UNDERCARRIAGE	New	200.00	40.00
11	TO DO COMPUTER WHEEL ALIGNMENT AFTER REPAIR	New	80.00	60.00
Gross Labour Cost (S\$)			4,030.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >