

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000047/AVP3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00002772201

Claimant Vehicle No : SLG6538Y **Insured Vehicle No :** YP3507E

Date of Loss: 30/12/2022 Nature of Claim: TP Claim No: SNM23D200009/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG6538Y**

Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4408762

Reg. Date: 10/10/2016 (Man. Year: 2016) Chassis No: RU11208761

Colour: Red Odometer: 319086 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,465.68	5,458.48	5,007.20	47.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	1,930.00	2,050.00	51.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,445.68	7,388.48	7,057.20	48.85
Approved Total (Overridden) (\$\$)		5,900.00		
Nett Amount (\$\$)	14,445.68	5,900.00	8,545.68	59.16

INSPECTION

Date of Assignment: 03/01/2023

Date Inspected: 03/01/2023 Inspected At: 1 KAKI BUKIT AVE 6
#01-82 AUTOBAY
SINGAPORE 417883
Repairer: Sin Yu Sin Workshop (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG6538Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	880.20 FL	*745.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	49.00 FL	*49.00 FL
4	1		*REAR BUMPER REFLECTOR	O/S Cracked	282.20 FL	*141.10 FL
5	2		*REAR BUMPER SIDE APRON	Repair	390.00 FL	*- FL
6	1		*REAR END PANEL	Dented	585.40 FL	*585.40 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	98.40 FL	*98.40 FL
8	1		*REAR END PANEL BUZZER	Damaged	85.20 FL	*85.20 FL
9	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	95.90 FL	*- FL
10	1		*TAILLAMP	O/S Cut	949.20 FL	*474.60 FL
11	1		*TAILGATE	Distorted	1,100.60 FL	*1,100.60 FL
12	1		*TAILGATE LOCK	Damaged	182.50 FL	*182.50 FL
13	1		*TAILGATE WEATHERSTRIPE	Cut	168.40 FL	*168.40 FL
14	1		*TAILGATE INNER TRIM BOARD	Cracked	285.60 FL	*285.60 FL
15	2		*TAILGATE DAMPER	Not Necessary	557.80 FL	*- FL
16	1		*TAILGATE REFLECTOR	O/S Cracked	826.40 FL	*413.20 FL
17	1		*TAILGATE OUTER GARNISH	Cracked	325.90 FL	*325.90 FL
18	1		*TAILGATE OUTER GARNISH CHROME	Not Necessary	194.10 FL	*- FL
19	1		*TAILGATE GLASS MOULDING	Necessary	120.40 FL	*120.40 FL
20	1		*HONDA LOGO	Necessary	30.40 FL	*30.40 FL
21	1		*REAR FENDER INNER TRIM	O/S Deformed	710.40 FL	*305.20 FL
22	2		*REAR FENDER ARC GARNISH	Not Necessary	392.00 FL	*- FL
23	1		*SPARE TYRE PANEL	Repair	1,130.40 FL	*- FL
24	1		*SPARE TYRE PANEL TOP COVER	Deformed	306.60 FL	*306.60 FL
25	1		*SPARE TYRE PANEL UNDERCOVER	Torn	225.10 FL	*225.10 FL
26	1		*TOOLS TRAY SPONGE	Cracked	285.40 FL	*285.40 FL
27	1		*REAR EXHAUST PIPE	Not Necessary	598.60 FL	*- FL
28	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	34.40 FL	*- FL
29	1		*REAR EXHAUST PIPE GASKET	Not Necessary	32.90 FL	*- FL
30	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	124.10 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
32	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
33	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*REAR BUMPER LOWER CHROME MOULDING	Cut	300.00 FS	*200.00 FS
35	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
38	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
40	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
41	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
42	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
43	1		*REAR FENDER ARC GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*SPARE TYRE PANEL UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
45	1		*VEZEL WORDING	Necessary	45.10 FL	*45.10 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	12,699.60	6,653.10
				- List Item Discount on L Items 20.00/20.00% (S\$)	2,233.92	1,194.62
				Total Parts (S\$)	10,465.68	5,458.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	800.00
2	SPRAY PAINTING	New	1,400.00	700.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
10	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			3,980.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >