

Vehicle No. SLG6538Y

HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR NUMBER PLATE LAMP @\$38.5 <i>new</i>		77.00	X
2	REAR BUMPER <i>Dehnd</i>		880.20	745
3	REAR BUMPER SIDE HOLDER @24.5 <i>new</i>		49.00	/
4	REAR BUMPER REFLECTOR @141.1 <i>RH could</i>		282.20	141.10
5	REAR BUMPER SIDE APRON @195 <i>Repis</i>		390.00	X
6	REAR END PANEL <i>Dehnd</i>		585.40	/
7	REAR END PANEL TOP GARNISH <i>Dehnd</i>		98.40	/
8	REAR END PANEL BUZZER <i>Damaged</i>		85.20	/
9	REAR END PANEL ANTENNA SENSOR <i>new</i>		95.90	X
10	TAILLAMP @474.6 <i>lt RH</i>		949.20	474.60
11	TAILGATE <i>Distorted</i>		1100.60	/
12	TAILGATE LOCK <i>Dehnd</i>		182.50	/
13	TAILGATE WEATHERSTRIPE <i>lt</i>		168.40	/
14	TAILGATE INNER TRIM BOARD <i>cracked</i>		285.60	/
15	TAILGATE DAMPER @278.9 <i>new</i>		557.80	X
16	TAILGATE REFLECTOR @413.2 <i>RH could</i>		826.40	413.20
17	TAILGATE OUTER GARNISH <i>cracked</i>		325.90	/
18	TAILGATE OUTER GARNISH CHROME <i>new</i>		194.10	X
19	TAILGATE GLASS MOULDING <i>new</i>		120.40	/
20	HONDA LOGO <i>new</i>		30.40	/
21	REAR FENDER INNER TRIM @305.20 <i>RH Dehnd</i>		710.40	305.20
22	REAR FENDER ARC GARNISH @196 <i>new</i>		392.00	X
23	SPARE TYRE PANEL <i>Repis</i>		1130.40	X
24	SPARE TYRE PANEL TOP COVER <i>Dehnd</i>		306.60	/
25	SPARE TYRE PANEL UNDERCOVER <i>to/n</i>		225.10	/
26	TOOLS TRAY SPONGE <i>cracked</i>		285.40	/
27	REAR EXHAUST PIPE		598.60	X
28	REAR EXHAUST PIPE MOUNTING		34.40	X
29	REAR EXHAUST PIPE GASKET		32.90	X
30	REAR EXHAUST PIPE HEAT SHIELD		124.10	X
31	<i>Vezel Working new</i>			
			11124.50	
		less	20%	20%
			2224.90	
			8899.60	
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE <i>new</i>		30.00	X
2	REAR NUMBER PLATE HOLDER <i>new</i>		30.00	X
3	REAR BUMPER CLIPS <i>new</i>		50.00	30
4	REAR BUMPER LOWER CHROME MOULDING <i>lt</i>		300.00	200
5	REVERSE SENSOR <i>Damaged</i>		280.00	200
6	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		20.00	/
7	REAR END PANEL SEALANT <i>new</i>		60.00	/
8	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>		50.00	30
9	TAILGATE OUTER GARNISH CLIPS <i>new</i>		30.00	20
10	TAILGATE GLASS SEALANT <i>new</i>		60.00	/
11	REAR CAMERA <i>new</i>		480.00	X
12	REAR FENDER INNER TRIM CLIPS <i>new</i>		60.00	30
13	REAR FENDER ARC GARNISH CLIPS <i>new</i>		50.00	X
14	SPARE TYRE PANEL UNDERCOVER CLIPS <i>new</i>		30.00	/
Total Parts			1530.00	

5973.10

A778.48

680

Vehicle No. SLG6538Y

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1500.00	800
2	SPRAY PAINTING	1400.00	700
3	WIRING	100.00	30
4	TO APPLY TUFF COAT	150.00	60
5	TO REMOVE UPHOLSTERY	150.00	60
6	TO TRANSFER TAILGATE FITTINGS	150.00	60
7	TO REMOVE TAILGATE GLASS	180.00	120
8	TO REMOVE REVERSE SENSOR	100.00	50
9	TO REMOVE REAR CAMERA	100.00	50
10	TO REMOVE REAR EXHAUST PIPE	150.00	X
	Labour Total :	3980.00	
	TOTAL (PARTS & LABOUR):	14409.60	

Total: 7388.48

L/S : 5.9K.

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: