

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23000053/KWY3Q2**Date:** 18/04/2023**REFERENCE**

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SBA4K **Insured Vehicle No :** SFC3188K
 Date of Loss: 27/12/2022 Nature of Claim: TP Claim No: DMPC2200681H.02/GK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBA4K**
 Make & Model: TOYOTA NOAH, 2.0 X CVT (A) Engine No: 3ZRB917502
 Reg. Date: 19/01/2017 (Man. Year: 2016) Chassis No: ZRR800258021
 Colour: Metallic Brown Odometer: 60481 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,485.00	2,430.50	1,054.50	30.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,510.00	720.00	32.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,715.00	3,940.50	1,774.50	31.05
Approved Total (Overridden) (S\$)		3,150.00		
(S\$)	5,715.00	3,150.00	2,565.00	44.88
+ GST 8.00/8.00% (S\$)	457.20	252.00	205.20	44.88
Nett Amount (S\$)	6,172.20	3,402.00	2,770.20	44.88

INSPECTION

Date of Assignment: 03/01/2023
 Date Inspected: 04/01/2023 Inspected At: Tropical Success Auto Care (HQ)
 BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2
 Singapore 569535
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts: M1-MPV	TOYOTA NOAH 2.0 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SBA4K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR WINDSCREEN MOULDING	Necessary	162.00 FL	*162.00 FL
2	1		*REAR BOOT	Bent	1,700.00 FL	*1,700.00 FL
3	1		*REAR BOOT RUBBER (50%)	Dented / Distorted	263.25 FS	*175.50 FS
4	1		*REAR END PANEL TOP GARNISH	Buckled	230.00 FL	*230.00 FL
5	1		*REAR WHEEL PANEL TOP COVER	Serviceable	998.00 FL	*- FL
6	1		*REAR BUMPER	Bent	648.00 FL	*648.00 FL
7	1		*REAR BUMPER TOWING COVER	Serviceable	33.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR (LH)	Serviceable	68.00 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER	Serviceable	190.00 FL	*- FL
10	1		*SET REAR BUMPER PARKTRONIC SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,492.25	3,115.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,007.25	685.00
Total Parts (\$\$)	3,485.00	2,430.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT REAR WINDSCREEN	New	250.00	120.00
2	HEAT /WELD /BEATING/PULL/STRAIGHTEN /ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	800.00	600.00
3	REMOVE AND TRANSFER REAR BOOT NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
4	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
5	REMOVE AND REFIT REAR BOOT ,REAR BOOT RUBBER ,REAR END PANEL TOP GARNISH ,REAR WHEEL PANEL TOP COVER ,REAR BUMPER ,REAR BUMPER PARKTRONIC SENSOR ,REAR BUMPER TOWING COVER ,REAR BUMPER REFLECTOR (LH),REAR BUMPER SIDE RETAINERS }	New	0.00	0.00
6	DIAGNOSTIC AND RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT	New	100.00	50.00
7	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS	New	80.00	20.00
8	UNDER COATING ON REAR DAMAGED PORTION	New	200.00	60.00
9	PUTTY/PRIMER APPLICATION SPRAY PAINTING REAR BOOT ,REAR BUMPER ,REAR BUMPER TOWING COVER	New	800.00	660.00
			Gross Labour Cost (S\$)	2,230.00
				1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >