

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SG 1889J

Qty	Description of Parts	Condition	Recommended (\$)
	REPLACEMENT OF PARTS		
1	30400005 = MIRROR VIEW ASSY.FRT.O/S.E5&6	CRACKED	562.90
			562.90
	<u>LABOUR</u>		
	LABOUR. }		244.40
	SPRAY PAINTING. }		-
			244.40
	GRAND TOTAL		807.30

RECOMMENDED COST OF REPAIRS	807.30
-----------------------------	--------

Report Ref No. CS/FCI23000056/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

XXX.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser