

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23000057/KWY3E2**Date:** 08/02/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001959295

Claimant Vehicle No : SNB294S**Insured Vehicle No :** SLE921Z

Date of Loss: 30/12/2022

Nature of Claim: TP

Claim No: 297840

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNB294S**

Make & Model: TOYOTA TOYOACE, 2.2 (A)

Engine No: MR20406515W

Reg. Date: 21/04/2016 (Man. Year: 2016)

Chassis No: SJNFBAJ11U1651369

Colour: Metallic Black

Odometer: 122608 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,151.12	1,915.94	9,235.18	82.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	965.00	2,665.00	73.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,781.12	2,880.94	11,900.18	80.51
+ GST 8.00/8.00% (S\$)	1,182.49	230.48	952.01	80.51
Nett Amount (S\$)	15,963.61	3,111.42	12,852.19	80.51

INSPECTION

Date of Assignment: 05/01/2023

Date Inspected: 04/01/2023 Inspected At:

Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Feb 2023)	
Parts:	N/A	TOYOTA TOYOACE 2.2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB294S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	3,306.00 FL	*- FL
2	2		*REAR TAILGATE ABSORBER	Serviceable	501.40 FL	*- FL
3	1		*REAR TAILGATE LOCK	Repair	176.30 FL	*- FL
4	1		*REAR TAILGATE CENTRE PANEL	Serviceable	350.00 FL	*- FL
5	1		*REAR TAILGATE EMBLEM	Not Necessary	94.00 FL	*- FL
6	1		*REAR TAILGATE LOGO QASHQAI	Not Necessary	94.00 FL	*- FL
7	1		*REAR TAILGATE LOGO PURE DRIVE	Not Necessary	94.00 FL	*- FL
8	1		*REAR TAIL LAMP RH	Serviceable	323.70 FL	*- FL
9	1		*REAR TAIL LAMP LH	Serviceable	323.70 FL	*- FL
10	1		*REAR BUMPER	Cracked / Buckled	717.00 FL	*717.00 FL
11	1		*REAR BUMPER SIDE RETAINER LH	Distorted	47.70 FL	*47.70 FL
12	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	47.70 FL	*- FL
13	1		*REAR BUMPER SPONGE	Cracked	141.40 FL	*141.40 FL
14	1		*REAR REINFORCEMENT	Bent	691.50 FL	*619.20 FL
15	1		*REAR BUMPER REFLECTOR LH	Serviceable	61.90 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Serviceable	61.90 FL	*- FL
17	1		*REAR LAMP LH	Serviceable	282.30 FL	*- FL
18	1		*REAR LAMP RH	Serviceable	282.30 FL	*- FL
19	1		*REAR END PANEL	Repair	482.60 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Serviceable	79.30 FL	*- FL
21	1		*REAR FENDER LH	Repair	1,347.90 FL	*- FL
22	1		*REAR FENDER INNER SHIELD LH	Serviceable	202.00 FL	*- FL
23	1		*REAR FENDER RH	Repair	1,347.90 FL	*- FL
24	1		*REAR FENDER INNER SHIELD RH	Serviceable	202.00 FL	*- FL
25	1		*TOWING COVER	Dented	31.30 FL	*31.30 FL
26	1		*REAR TAILGATE WEATHERSHIELD	Serviceable	167.00 FL	*- FL
27	2		*REAR REINFORCEMENT BRACKET LH & RH	Bent	300.00 FL	*300.00 FL
28	1		*SET REAR NUMBER PLATE WITH FRAME	Serviceable	50.00 FS	*- FS
29	1		*SET REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
30	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
31	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	35.00 FS	*- FS
32	1		*SET REAR INNER COMPARTMENT CLIPS	Not Necessary	35.00 FS	*- FS
33	1		*SET REAR BOOT INNER TRIM BOARD CLIPS	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,326.80	2,101.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,175.68	185.66
Total Parts (\$\$)	11,151.12	1,915.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,200.00	450.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT, WELD AND REALIGN ACCIDENT AFFECTED AREA-FRONT & REAR	New	1,200.00	400.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	120.00	15.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	0.00
5	TO REMOVE / REFIX / REPLACE REAR REVERSE CAMERA	New	150.00	50.00
6	TO REMOVE / REPLACE REAR INNER COMPARTMENT, MECHANISM, CAR SEAT TO FACILITIES REPAIR	New	250.00	0.00
7	TO REMOVE / REFIX REVERSE SENSOR	New	120.00	50.00
8	TO REMOVE / REFIX REVERSE CAMERA	New	120.00	0.00
9	TO REMOVE / REFIX / REPLACE REAR TAILGATE TO NEW, REAR TOP SPOILER MECHANISM & ETC	New	200.00	0.00
10	TO REMOVE / REFIX / REPLACE REAR WINDSCREEN TO NEW TAILGATE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,630.00	965.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >