



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1550P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILLAMP RH	GRAZED / DEFACED	422.10	422.10
1	RR BUMPER	DENTED / BROKEN	682.30	682.30
1	RR BUMPER SIDE GARNISH RH	BROKEN	136.60	136.60
6	RR BUMPER CLIP @\$3.40	NECESSARY	20.40	20.40
2	RR BUMPER RETAINER R/L @\$72.80	BROKEN / NECESSARY	145.60	145.60
1	RR FENDER RH	DENTED / BUCKLED	1,508.10	1,366.00
1	RR FENDER INNER PANEL RH	TO REPAIR SEE LABOUR	832.60	-
1	RR RIM COVER RH	NOT NECESSARY	162.80	-
1	RR FENDER INNER PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER WHEEL HOUSE RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-977.63	-693.25
			2,932.87	2,079.75
<u>SPECIAL NETT ITEMS</u>				
1	RR TYRE LH (SN)	NOT NECESSARY	250.00	-
1	RR QUARTER GLASS SEALANT RH (SN)	NECESSARY	50.00	40.00
1	RR FENDER PANEL SEALANT RH (SN)	NECESSARY	50.00	40.00
			350.00	80.00
<u>LABOUR</u>				
	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK AFFECTED ELECTRICAL WIRING SYSTEM.		50.00	30.00
	TO REMOVE AND REINSTALL RHR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS.		100.00	80.00
	TO REMOVE AND REINSTALL RHR QUARTER GLASS FOR NECESSARY REPAIRS.		100.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR FENDER INNER PANEL RH AND RR FENDER WHEEL HOUSE RH.		1,000.00	770.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	500.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		30.00	30.00
			2,340.00	1,490.00
GRAND TOTAL			5,622.87	3,649.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS3/LPC22009402/Dvy3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.