

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000062/UNY3E2**Date:** 12/04/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00077192203

**Claimant Vehicle
No :** JTL4492**Insured Vehicle
No :** GBF1809Y

Date of Loss: 30/11/2022

Nature of Claim: TP

Claim
No: SNM22D209206/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **JTL4492**

Make & Model: KAWASAKI Z900, 948cc

Engine No: ZR900BE018632

Reg. Date: 03/06/2019 (Man. Year: 2017)

Chassis No: JKAZR900BBDA26506

Colour: Black

Odometer: 0 km

Engine Capacity: 948 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-17

Rear Tyre Size: 180/55-17

Front Left Side: Pirelli 7 mm

Rear Left Side: Pirelli 7 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,447.50	2,610.00	2,837.50	52.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	100.00	500.00	83.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,047.50	2,710.00	3,337.50	55.19
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	6,047.50	2,100.00	3,947.50	65.27

INSPECTION

Date of Assignment: 04/01/2023

Date Inspected: 04/01/2023 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Apr 2023)	
Parts:	N/A	KAWASAKI Z900 948cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JTL4492)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE PEDAL	Not Necessary	325.00 FL	*- FL
2	1		*FRONT FOOTREST	Not Necessary	295.00 FL	*- FL
3	1		*EXHAUST ASSY	Damaged	2,880.00 FS	*2,500.00 FS
4	1		*REAR FOOTREST	Not Necessary	285.00 FL	*- FL
5	1		*SET REAR NUMBER PLATE	Cracked	38.00 FS	*10.00 FS
6	1		*SET STICKER	Scratched	285.00 FS	*100.00 FS
7	1		*ENGINE PROTECTOR (CUT)	Not Consistent With The Impact	450.00 FS	*- FS
8	1		*SET CRASH BAR (CUT)	Not Consistent With The Impact	980.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,538.00	2,610.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	90.50	0.00
Total Parts (\$\$)	5,447.50	2,610.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	520.00	100.00
Gross Labour Cost (\$\$)			600.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >