

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000086/UYA3Q2**Date:** 22/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220003507
Claimant Vehicle No :	SKM3930Y	Insured Vehicle No :	SNE4444J
Date of Loss:	29/12/2022	Nature of Claim:	TP
		Claim No:	4514720830SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM3930Y	Engine No:	27091030336357
Make & Model:	MERCEDES-BENZ A180 R17, 1.6 (A)	Chassis No:	WDD1760422J235177
Reg. Date:	26/02/2014 (Man. Year: 2013)	Odometer:	141702 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,187.30	5,667.50	3,519.80	38.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,410.00	1,440.00	50.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,037.30	7,077.50	4,959.80	41.20
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	12,037.30	5,600.00	6,437.30	53.48
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	04/01/2023	
Date Inspected:	04/01/2023	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S HEADLAMP	Cracked	1,093.00 FL	*1,093.00 FL
2	1		*N/S FRONT FENDER	Dented / Bent	845.00 FL	*845.00 FL
3	1		*N/S FRONT FENDER INNER SHIELD	Distorted	245.00 FL	*245.00 FL
4	1		*FRONT BUMPER	Deformed / Warped	1,406.00 FL	*1,406.00 FL
5	1		*N/S FRONT BUMPER SIDE RETAINER	Cracked	45.00 FL	*45.00 FL
6	1		*N/S FRONT BUMPER BRACKET	Not Necessary	246.00 FL	*- FL
7	1		*N/S FRONT FOG LAMP COVER	Not Necessary	194.00 FL	*- FL
8	1		*N/S FRONT BUMPER SENSOR	Serviceable	288.00 FL	*- FL
9	4		*FRONT BUMPER SENSOR RING	Necessary	52.00 FL	*52.00 FL
10	4		*FRONT BUMPER SENSOR BRACKET	Not Necessary	220.00 FL	*- FL
11	1		*N/S FRONT RIM	Warped	823.00 FL	*823.00 FL
12	1		*N/S FRONT SHOCK ABSORBER	Not Necessary	707.00 FL	*- FL
13	1		*N/S FRONT LOWER ARM	Not Necessary	561.00 FL	*- FL
14	1		*N/S FRONT KNUCKLE ARM	Warped	947.00 FL	*947.00 FL
15	1		*N/S FRONT WHEEL HUB	Damaged	354.00 FL	*354.00 FL
16	1		*N/S FRONT WHEEL BEARING	Damaged	265.00 FL	*265.00 FL
17	1		*N/S FRONT FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*60.00 FS
18	1		*N/S FRONT FENDER INNER SHIELD RIVETS	Not Necessary	80.00 FS	*- FS
19	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
20	1		*FRONT BUMPER RIVET	Necessary	80.00 FS	*80.00 FS
21	1		*N/S WING MIRROR	Repair	1,606.00 FL	*- FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	10,177.00 6,275.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	989.70 607.50
					Total Parts (\$\$)	9,187.30 5,667.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS HEADLAMP & WIRING	New	50.00	20.00
2	TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER }	New	250.00	80.00
3	TO RE-CALIBRATE HEADLAMP MODULE }	New	280.00	0.00
4	TO CONDUCT COMPETERIZE FOUR WHEEL ALIGNMENT	New	120.00	120.00
5	TO RUSTPROOF ON DAMAGED PARTS	New	150.00	30.00
6	TO FIT SENSOR ON NEW BUMPER	New	50.00	40.00
7	TO FIT TYRE ON NEW RIM INCLUDE BALANCING	New	50.00	0.00
8	TO REPLACE N/S UNDERCARRIAGE	New	300.00	120.00
9	TO REPAIR INNER PANEL ,ACCIDENT DAMAGE AREA ,REPLACEMENT OF PARTS AND ALIGN THE SAME	New	800.00	400.00
10	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	800.00	600.00
Gross Labour Cost (S\$)			2,850.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >