

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	SPECTION REP	ORT	
	SOMPO INSURAN	CE SINGAPORE PL	F	Ref:	CS3/SMO23000087/Uqy3e2
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND PRE 048623	[Date:	11/01/2023
			(Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBJ 4521K	Veh. Inspected		GBF 9817X
	Policy No.		Coverage (\$)		0.00
	Claim No.	CMTD2204778/SYH	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		04/01/2023
2.		Vehicle Par	ticulars & Condition	on	
	Make & Model	NISSAN NV350 (M)	c.c		2488
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	JN1MC2E26Z0007703	Colour		GREY
	Odometer	130638 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3.		Cond	itions of Tyres		
		Size	Make		Balance
	R/H Front Tyre	195 R15	FALKEN		6 mm
	L/H Front Tyre	195 R15	FALKEN		6 mm
	R/H Rear Tyre	195 R15	FALKEN		6 mm
	L/H Rear Tyre	195 R15	FALKEN		6 mm
4.		Descrip	tion of Damages		
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.		Gene	ral Information		
5.	Accident Date	Gene 27/12/2022	ral Information	ime	04/01/2023 (02:18 PM)
5.	Accident Date Survey held at		Inspect Date / T	ime	04/01/2023 (02:18 PM)
5.		27/12/2022	Inspect Date / T	ime	04/01/2023 (02:18 PM)
5. 5a.	Survey held at	27/12/2022 1 Kaki Bukit Avenue 6 #01-15 A POLYMATH GARAGE PTE LTI	Inspect Date / T	ime	04/01/2023 (02:18 PM)
	A) THE INSPECTION IN THE REPAIRER WITH T	27/12/2022 1 Kaki Bukit Avenue 6 #01-15 A POLYMATH GARAGE PTE LTI	Inspect Date / To Autobay D Remarks //THOUT PREJUDICED AT THE TIME OF STIMATE. E PHOTOGRAPHS.	E" BAS INSPE	IS. CTION.
	A) THE INSPECTION IN THE REPAIRER WITH T	27/12/2022 1 Kaki Bukit Avenue 6 #01-15 A POLYMATH GARAGE PTE LTI DN WAS CONDUCTED ON A "W STIMATE WAS NOT PRESENTE VAS TOLD TO PREPARE THE E EASE FIND DAMAGED VEHICL ED REPAIR COST OF THE DAM	Inspect Date / To Autobay D Remarks //THOUT PREJUDICED AT THE TIME OF STIMATE. E PHOTOGRAPHS.	E" BAS INSPE	IS. CTION.

Report Ref No. CS3/SMO23000087/Uqy3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser