

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23000090/TQY3Q2**Date:** 03/02/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP000977	
Claimant Vehicle No :	SHD6655E	Insured Vehicle No :	SMY8639U	
Date of Loss:	02/01/2023	Nature of Claim:	TP	Claim No: M2300054

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6655E	Engine No:	65192433261175
Make & Model:	MERCEDES-BENZ E220, 2.1 CDI (A)	Chassis No:	WDD2120012B307939
Reg. Date:	23/03/2016 (Man. Year: 2015)	Odometer:	1087857 km
Colour:	White		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	205/60R16
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,732.00	1,596.00	1,136.00	41.58
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,000.00	680.00	320.00	32.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,743.00	2,287.00	1,456.00	38.90
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	3,743.00	1,850.00	1,893.00	50.57
+ GST 8.00/8.00% (S\$)	299.44	148.00	151.44	50.57
Nett Amount (S\$)	4,042.44	1,998.00	2,044.44	50.57

INSPECTION

Date of Assignment:	04/01/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/01/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2023)
Parts:	143	MERCEDES-BENZ E220 2.1 CDI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6655E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	1,510.00 FL	*1,510.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,150.00 FL	*- FL
3	1		*REAR BUMPER LOWER BRACKET LH	Not Necessary	135.00 FL	*- FL
4	1		*REAR BUMPER LOWER BRACKET RH	Not Necessary	135.00 FL	*- FL
5	1		*REVERSE SENSOR	Cracked	388.00 F	*388.00 F
						F=Franchise part. L=ListItemDisc.
Sub Total (S\$)					3,318.00	1,898.00
- List Item Discount on L Items 20.00/20.00% (S\$)					586.00	302.00
Total Parts (S\$)					2,732.00	1,596.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	400.00
2	SPRAYPAINT	New	400.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	100.00	30.00
Gross Labour Cost (\$\$)			1,000.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >