

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000091/SQP3M4**Date:** 08/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00197952100

Claimant Vehicle No : SFH1232C **Insured Vehicle No :** SFW89C

Date of Loss: 28/12/2022 Nature of Claim: TP Claim No: SNM22D209367/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH1232C**

Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A13800156

Reg. Date: 06/03/2009 (Man. Year: 2008) Chassis No: JHMRN68609S200156

Colour: Blue Odometer: 251382 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,685.36	2,870.56	3,814.80	57.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,980.00	1,400.00	41.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,065.36	4,850.56	5,214.80	51.81
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	10,065.36	3,800.00	6,265.36	62.25

INSPECTION

Date of Assignment: 04/01/2023

Date Inspected: 04/01/2023 Inspected At: 2020 SPRAY PAINTING PTE LTD
8 KAKI BUKIT AVENUE 4,
#03-19, PREMIER @ KAKI BUKIT, SINGAPORE
415875

Estimated Period of Repair: 5.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFH1232C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	668.40 FL	*668.40 FL
2	2		*REAR BUMPER SIDE HOLDER @34.10	Necessary	68.20 FL	*68.20 FL
3	1		*REAR BUMPER TOW COVER	Deformed	39.40 FL	*39.40 FL
4	1		*REAR END PANEL	Dented	459.10 FL	*459.10 FL
5	1		*REAR END PANEL INNER MEMBER	Repair	186.90 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	216.70 FL	*216.70 FL
7	2		*TAILLAMP @366.50	Not Necessary	733.00 FL	*- FL
8	2		*TAILLAMP PANEL @390.10	Not Necessary	780.20 FL	*- FL
9	1		*TAILGATE	Dented	903.40 FL	*903.40 FL
10	1		*TAILGATE LOCK	Damaged	189.40 FL	*189.40 FL
11	1		*TAILGATE WEATHERSTRIPE	Not Necessary	195.90 FL	*- FL
12	2		*TAILGATE DAMPER @212.10	Not Necessary	424.20 FL	*- FL
13	1		*TAILGATE INNER TRIM BOARD	Not Necessary	285.10 FL	*- FL
14	1		*TAILGATE OUTER GARNISH	Not Necessary	239.80 FL	*- FL
15	1		*TAILGATE GLASS MOULDING	Necessary	124.10 FL	*124.10 FL
16	1		*HONDA LOGO	Not Necessary	45.90 FL	*- FL
17	1		*STREAM WORDING	Necessary	49.10 FL	*49.10 FL
18	2		*FLOOR PANEL TOP COVER	Not Necessary	482.20 FL	*- FL
19	1		*REAR FENDER INNER TRIM BOARD @295.40	N/s Cracked	590.80 FL	*295.40 FL
20	1		*REAR EXHAUST PIPE	Not Necessary	678.10 FL	*- FL
21	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.80 FL	*- FL
22	1		*REAR EXHAUST PIPE GASKET	Not Necessary	32.60 FL	*- FL
23	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	115.90 FL	*- FL
24	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
25	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
26	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
28	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
31	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
32	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
33	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,194.20	3,473.20
- List Item Discount on L Items 20.00/20.00% (S\$)	1,508.84	602.64
Total Parts (S\$)	6,685.36	2,870.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,380.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >