



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SKP 6364X

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	R/F DOOR COVER (NPA)	SERVICEABLE	-
1	R/F OUTER DOOR SEAL (WCP)	NECESSARY	165.00
1	R/R DOOR (WCP)	BENT	1,350.00
1	R/R DOOR COVER (NPA)	SERVICEABLE	-
1	R/R OUTER DOOR SEAL (WCP)	NECESSARY	215.00
1	RIGHT FRONT DOOR (WCP)	BENT	1,350.00
	COST PLUS 10%		308.00
			3,388.00
	<u>LABOUR</u>		
	CHK/ERASE FAULT CODE AFTER REPAIR.		80.00
	47.0 WU X 50.00 SGD/H.		235.00
	LABOUR COST 65.0 WU X 50.00 SGD/H.		325.00
	MATERIAL COST.		118.89
			758.89
	GRAND TOTAL		4,146.89
RECOMMENDED COST OF REPAIRS			4,146.89

Report Ref No. CS/MSG23000092/Kwy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.