

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23000097/RVP3Q2**Date:** 03/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00019602201
<b>Claimant Vehicle No :</b>	SLA7959R	<b>Insured Vehicle No :</b>	SMW158D
Date of Loss:	29/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209376/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLA7959R</b>	Engine No:	F503H532B38A15A
Make & Model:	BMW X1 SDRIVE18I, 1.5 LED NAV (A)	Chassis No:	WBAHS120X05J97825
Reg. Date:	21/08/2017 (Man. Year: 2017)	Odometer:	49084 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,447.60	1,346.30	101.30	7.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,635.00	4,601.00	3,034.00	39.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,082.60</b>	<b>5,947.30</b>	<b>3,135.30</b>	<b>34.52</b>
<b>+ GST 8.00/8.00% (S\$)</b>	726.61	475.78	250.83	34.52
<b>Nett Amount (S\$)</b>	<b>9,809.21</b>	<b>6,423.08</b>	<b>3,386.13</b>	<b>34.52</b>

**INSPECTION**

Date of Assignment:	04/01/2023	Performance Motors Limited (Alexandra)
Date Inspected:	06/02/2023 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	5.0 days	Singapore 159941

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2023)
Parts:	M1-SUV	BMW X1 SDRIVE18I 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA7959R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 7.5X18Y SPK 569	Scratched	1,066.70 FS	*1,066.70 FS
3	1		*HUB CAP WITH CHROME EDGE	Not Necessary	31.30 FS	*- FS
4	1		*REAR RH WHEEL ARCH TRIM	Scratched	163.40 FS	*163.40 FS
5	1		*TORX SCREW SELF TAPPING M10X70	Necessary	7.40 FS	*7.40 FS
6	2		*TORX SCREW SELF TAPPING M10X70	Necessary	14.80 FS	*14.80 FS
7	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
Total Parts (S\$)						1,447.60 1,346.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE REAR BUMPER ,RIGHT SIDE FENDER ,RIGHT REAR DOOR ATTACHMENT ETC TO CARRY OUT REPAIRING WORK AND REPLACE DAMAGE PARTS ITEM	New	3,400.00	1,700.00
2	PAINTING REAR BUMPER ,RIGHT REAR SIDE FENDER AND RIGHT REAR DOOR	New	3,256.00	1,972.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	504.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING RIGHT REAR	New	94.00	89.00
<b>Gross Labour Cost (S\$)</b>			<b>7,635.00</b>	<b>4,601.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >