

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 05 Jan 2023

Preliminary Advice

Vehicle No	: SJG8176T	Accident Date	: 27/12/2022
Make	: TOYOTA ESTIMA	Policy No.	: DMPCSNW00146822204
Assignment Date	: 04/01/2023	Excess	: S\$0.00
Date of Inspection	: 05/01/2023	Est. Duration of Repair	: 7
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

RePAIRER'S Estimate (Gross)	:S\$	9,073.62
Revised Amount	:S\$	7,288.42
Check Items (Estimated)	:S\$	1,697.00
Total	:S\$	8,985.42
Lump Sum Repair	:S\$	6,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	8,500.00
COE / PARF Rebate	:S\$	2,013.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,487.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$6,000.00 ON LUMP SUM BASIS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.