

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SING	APORE) PTE LTD	Ref:	CS3/ASM23000102/Svp3e2	
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date:	13/02/2023	
	ATTN: LOW GARN	ET	Code	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMS 8473L	Veh. Inspected	SMX 2060H	
	Policy No.	GA536916/1	Coverage (\$)	0.00	
	Claim No.	S2M04GEC	Excess (\$)	0.00	
	Assign From	LOW GARNET	Assign Date	04/01/2023	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ A180	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	WDD1760422J336536	Colour	BLACK	
	Odometer	156264 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	220/40-18	GOODYEAR	6 mm	
	L/H Front Tyre	220/40-18	GOODYEAR	6 mm	
	R/H Rear Tyre	220/40-18	GOODYEAR	6 mm	
	L/H Rear Tyre	220/40-18	GOODYEAR	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA			
5.	General Information				
	Accident Date	12/12/2022	Inspect Date / Time	04/01/2023 (04:30 PM)	
	Survey held at	68 KAKI BUKIT AVENUE 6, #01-	09 ARK@KB		
	Repairer ELITES PERFORMANCE				
5a.					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500-\$6,500				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/ASM23000102/Svp3e2

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser