

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM23000108/Rvp3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 09/01/2023 SINGAPORE 068811 ATTN: TEO KITTY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHA 2458A SLN 5988B Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S3M04HDS Excess (\$) 0.00 **TEO KITTY Assign Date** 04/01/2023 Assign From **Vehicle Particulars & Condition** 2. HONDA JAZZ 1.5 VTIR 1498 Make & Model c.c HIDDEN 2017 Engine No. Year of Reg. JHMGK5850HX201350 RED Chassis No. Colour 100187 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/55 R16 MICHELIN 6 mm **MICHELIN** L/H Front Tyre 185/55 R16 6 mm 185/55 R16 **MICHELIN** R/H Rear Tyre 6 mm **MICHELIN** L/H Rear Tyre 185/55 R16 6 mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. 5. **General Information** 31/12/2022 04/01/2023 (03:54 PM) Inspect Date / Time Accident Date 1 Bukit Batok Crescent #05-55, WCEGA Plaza, Singap Survey held at Repairer GARAGE B PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/ASM23000108/Rvp3e2

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

7 Working Days