

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM22007096/Rcp3-1 AXA INSURANCE PTE LTD Ref: C53/A5IVIZZUU/U90/ECV3III4 8 SHENTON WAY #24-01 AXA TOWER 40/00/2022 04/01/2023 Date: SINGAPORE 068811 ATTN: TEO KITTY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. XE 7188K YN 4452H Veh. Inspected Policy No. GA616584 Coverage (\$) 0.00 Claim No. S2M047BZ Excess (\$) 0.00 20/07/2022 04/01/2023 **TEO KITTY Assign Date** Assign From **Vehicle Particulars & Condition** 2. MITSUBISHI CANTER FEB21 c.c Make & Model 2998 HIDDEN 2013 Engine No. Year of Reg. FEB21EA00090 WHITE Chassis No. Colour 293764 KM Odometer Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/R15C DUNLOP 4 mm DUNLOP L/H Front Tyre 195/R15C 4 mm 195/R15C DUNLOP R/H Rear Tyre 4 mm **DUNLOP** 4 mm L/H Rear Tyre 195/R15C 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information** 21/07/2022 26/07/2022 (08:23 PM) Inspect Date / Time Accident Date 48 TOH GUAN ROAD EAST #02-126 ENTERPRISE HUB Survey held at SINCERELEAD GARAGE PTE LTD Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/ASM22007096/Ecy3m4

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

10 Working Days