

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23000117/UYA3Q2**Date:** 18/07/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001805754
Claimant Vehicle No :	GBE4774Z	Insured Vehicle No :	GBL9971B
Date of Loss:	30/12/2022	Nature of Claim:	TP
		Claim No:	202332004214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE4774Z	Engine No:	HR16040966D
Make & Model:	NISSAN NV200, 1.6 (A)	Chassis No:	VM20083335
Reg. Date:	11/12/2015 (Man. Year: 2015)	Odometer:	134185 km
Colour:	Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/75 R14	Rear Tyre Size:	175/75 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,405.71	3,940.06	3,465.65	46.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	2,010.00	700.00	25.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,115.71	5,950.06	4,165.65	41.18
Approved Total (Overridden) (S\$)		4,750.00		
Nett Amount (S\$)	10,115.71	4,750.00	5,365.71	53.04
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		5,336.75		

INSPECTION

Date of Assignment:	04/01/2023	
Date Inspected:	05/01/2023	Inspected At: Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jul 2023)	
Parts:	N/A	NISSAN NV200 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE4774Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	2,180.00 FL	*1,978.40 FL
2	1		*EMBLEM NISSAN	Necessary	65.70 FL	*65.70 FL
3	1		*EMBLEM NV200	Necessary	59.70 FL	*59.70 FL
4	1		*EMBLEM VANETTE	Necessary	112.30 FL	*112.30 FL
5	1		*REAR BOOT GARNISH	Not Necessary	287.70 FL	*- FL
6	1		*REAR BOOT INNER TRIM BOARD	Not Necessary	176.00 FL	*- FL
7	19		*REAR BOOT INNER TRIM BOARD CLIPS	Not Necessary	104.50 FL	*- FL
8	2		*REAR BOOT ADJUSTER RUBBER	Twisted	22.00 FL	*22.00 FL
9	2		*REAR BOOT STOPPER BUSH	Not Necessary	22.00 FL	*- FL
10	1		*REAR BOOT LOCK STRIKER	Not Necessary	33.00 FL	*- FL
11	1		*REAR BOOT INNER LOCK (L/H/R)	Damaged	116.50 FL	*116.50 FL
12	1		*REAR BOOT WEATHERSTRIP	Twisted	79.90 FL	*79.90 FL
13	1		*FLOOR PANEL (REAR)	Repair	1,634.70 FL	*- FL
14	1		*REAR FLOOR BOARD	Not Necessary	450.00 FL	*- FL
15	1		*REAR FLOOR TRIM	Not Necessary	479.70 FL	*- FL
16	1		*REAR END PANEL GARNISH	Twisted	78.20 FL	*78.20 FL
17	8		*REAR END PANEL GARNISH CLIP	Not Necessary	48.00 FL	*- FL
18	1		*REAR END PANEL	Badly Dented	631.90 FL	*481.00 FL
19	1		*REAR BUMPER	Dented	724.40 FL	*632.70 FL
20	5		*BUMPER CLIP	Necessary	27.50 FL	*27.50 FL
21	1		*REAR BUMPER SPONGE	Torn	97.90 FL	*97.90 FL
22	1		*REAR LAMP (L/H/R)	Cracked	281.60 FL	*281.60 FL
23	1		*LOCK GARNISH	Not Necessary	48.70 FL	*- FL
24	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
25	1		*BTL REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
26	2		*SEALANT (WINDSCREEN)	Necessary	70.00 FS	*40.00 FS
27	1		*STICKER 70KH/H	Necessary	10.00 FS	*10.00 FS
28	1		*STICKER 5 PAX	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,181.90	4,343.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	776.19	403.34
Total Parts (\$\$)	7,405.71	3,940.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO REMOVE REVERSE SENSOR	New	120.00	50.00
3	TO CHECK WIRING SYSTEM ,FOCUS LIGHTINGS	New	50.00	20.00
4	TO TRANSFER REAR BOOT FITTING	New	120.00	60.00
5	TO PROVIDE UNDER TURFCOAT	New	120.00	60.00
6	PANEL BEAT & REPAIR REAR DAMAGE	New	1,200.00	1,000.00
7	TO PUTTY AND RESPRAY AFFECTED PORTION	New	900.00	700.00
8	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	New	80.00	0.00
Gross Labour Cost (S\$)			2,710.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >