

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB23000118/UYA3Q2**Date:** 14/04/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKT7950B**Insured Vehicle No :** SLS8962D

Date of Loss: 30/12/2022

Nature of Claim: TP

Claim No: MFL2023D0000136

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKT7950B**

Make & Model: TOYOTA SIENTA, 1.5 (A)

Engine No: 1NZE777873

Reg. Date: 23/06/2015 (Man. Year: 2014)

Chassis No: NCP815219297

Colour: Purple

Odometer: 61063 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R14

Rear Tyre Size: 195/65 R14

Front Left Side: Michelin 6 mm

Rear Left Side: Linglong 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,640.10	12,042.37	18,597.73	60.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,070.00	3,280.00	1,790.00	35.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,710.10	15,322.37	20,387.73	57.09
Approved Total (Overridden) (S\$)		12,200.00		
Nett Amount (S\$)	35,710.10	12,200.00	23,510.10	65.84
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		13,126.75		

INSPECTION

Date of Assignment: 04/01/2023

Date Inspected: 04/01/2023 Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT7950B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,099.10 F	*- FL
2	1		*FRONT BUMPER	Distorted	1,233.20 F	*765.10 FL
3	1		*FRONT BUMPER SIDE RETAINER N/S	Cracked	98.10 F	*66.50 FL
4	1		*FRONT HEADLAMP N/S	Cracked	325.10 F	*325.10 FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*FRONT FENDER N/S	Distorted	845.10 F	*605.20 FL
7	1		*FRONT FENDER INNER SHIELD N/S	Distorted	299.20 F	*265.50 FL
8	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
9	1		*FRONT FENDER INNER VERTICAL GARNISH N/S	Not Necessary	145.00 F	*- FL
10	1		*FRONT FENDER INNER PANEL N/S	Repair	850.00 F	*- FL
11	1		*FRONT SPORT RIM N/S	Warped	1,200.00 FS	*300.00 FS
12	1		*FRONT SHOCK ABSORBER N/S	Bent	485.20 F	*399.20 FL
13	1		*FRONT KNUCKLE ARM N/S	Bent	655.20 F	*566.20 FL
14	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	450.00 F	*295.00 FL
15	1		*FRONT LOWER ARM N/S	Buckled	719.20 F	*511.20 FL
16	1		*FRONT DRIVE SHAFT N/S	Not Necessary	1,415.10 F	*- FL
17	1		*FRONT DOOR N/S	Distorted	1,645.10 F	*1,566.20 FL
18	1		*FRONT DOOR GLASS OUTER MOULDING N/S	Bent	182.40 F	*166.80 FL
19	1		*FRONT DOOR GLASS REGULATOR & MOTOR N/S	Bent / Jammed	847.90 F	*602.50 FL
20	2		*FRONT DOOR HINGES	Bent	210.00 F	*210.00 FL
21	1		*FRONT DOOR CHECKER N/S	Twisted	151.00 F	*142.00 FL
22	1		*FRONT DOOR INNER LOCK N/S	Dented / Jammed	683.20 F	*455.20 FL
23	1		*FRONT DOOR INNER TRIM BOARD N/S	Deformed / Torn	980.20 F	*815.20 FL
24	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS N/S	Necessary	50.00 F	*50.00 FL
25	1		*SET FRONT DOOR FRAME BLACK STICKER N/S	Necessary	115.00 F	*80.00 FL
26	1		*FRONT DOOR SPEAKER N/S	Not Necessary	288.90 F	*- FL
27	1		*FRONT DOOR INNER RUBBER N/S	Torn	366.50 F	*288.20 FL
28	1		*FRONT DOOR MIRROR ASSY N/S	Damaged	1,105.20 F	*980.10 FL
29	1		*FRONT DOOR OUTER PILLAR N/S	Dented	845.20 F	*715.20 FL
30	1		*FRONT DOOR INNER PILLAR N/S	Repair	699.10 F	*- FL
31	1		*FRONT DOOR INNER STEP GARNISH N/S	Warped	298.10 F	*266.50 FL
32	1		*FRONT DOOR OUTER HANDLE N/S	Broken	245.50 F	*220.00 FL
33	1		*FRONT DOOR SPEAKER N/S	Not Necessary	250.00 F	*- FL
34	1		*SLIDING DOOR N/S	Badly Dented	1,866.20 F	*1,615.30 FL
35	1		*SLIDING DOOR RUBBER N/S	Torn	322.20 F	*265.30 FL
36	1		*SET SLIDING DOOR FRAME BLACK STICKER N/S	Necessary	180.00 F	*80.00 FL
37	1		*SLIDING DOOR OUTER HANDLE N/S	Damaged	245.00 F	*220.00 FL
38	1		*SLIDING DOOR INNER TRIM BOARD N/S	Deformed / Torn	845.10 F	*755.10 FL
39	1		*SLIDING DOOR GLASS OUTER MOULDING N/S	Bent	122.80 F	*122.80 FL
40	1		*SLIDING DOOR INNER LOCK N/S	Jammed	399.60 F	*390.00 FL
41	1		*SLIDING DOOR ROLLER BRACKET N/S	Bent	102.00 F	*102.00 FL
42	1		*ROCKER PANEL N/S	Repair	945.10 F	*- FL
43	1		*ROCKER PANEL GARNISH N/S	Not fitted	922.50 F	*- FL
44	1		*SET ROCKER PANEL GARNISH CLIPS N/S	Not fitted	50.00 F	*- FL
45	1		*CENTRE PILLAR N/S	Badly Dented	1,021.20 F	*899.10 FL
46	1		*CENTRE PILLAR INNER TRIM N/S	Not Necessary	152.80 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER N/S	Repair	1,008.10 F	*- FL
48	1		*REAR WHEEL HUB BEARING N/S	Damaged	520.00 F	*350.00 FL
49	1		*REAR SHOCK ABSORBER N/S	Not Necessary	299.10 F	*- FL
50	1		*REAR AXLE BEAM	Not Necessary	1,855.60 F	*- FL
51	1		*REAR SPORT RIM N/S	Warped	450.00 FS	*300.00 FS
52	1		*FRONT SPORT RIM N/S	Repeated	450.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)				30,640.10	15,856.50
- List Item Discount on L Items 0.00/25.00% (\$\$)				0.00	3,814.13
Total Parts (\$\$)				30,640.10	12,042.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	100.00
3	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	150.00	120.00
4	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	250.00	120.00
5	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	100.00	60.00
6	TO DISMANTLE & REFIX SLIDING DOOR MECHANISM	New	100.00	60.00
7	TO SPRAY RUST PROOFING	New	180.00	120.00
8	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	New	120.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,200.00	1,200.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,400.00
Gross Labour Cost (S\$)			5,070.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >