



Case Details

Case Reference Number : TAX/01/23/2005
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5991B

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-20193-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 04/01/2023 02:25 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, RR BUMPER ASSY	1	525.40	525.40	25.00	394.05	Replace	1	394.05	Replace	de
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	12.00	24.00	25.00	18.00	Replace	2	18.00	Replace	ner
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	ner
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	ner
Standard	Main			PAD, RR BUMPER, CTR	3	12.00	36.00	25.00	27.00	Replace	0	0	Not Give	Xun
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	12.30	24.60	25.00	18.45	Replace	2	18.45	Replace	ner
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give	Xun
Standard	Main			RETAINER, RR BUMPER, RH	1	143.60	143.60	25.00	107.70	Replace	1	107.70	Replace	de
Standard	Main			SEAL, RR BUMPER , RH	1	128.00	128.00	25.00	96.00	Replace	0	0	Check	?
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	ner
Standard	Main			GUARD, RR BUMPER, LOWER	1	405.00	405.00	25.00	303.75	Replace	0	0	Not Give	Xun
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	42.20	42.20	25.00	31.65	Replace	0	0	Not Give	Xun
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Give	Kur
Total Spare Part Cost									8,193.42	Surveyor Total			3,872.93	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									8,193.42	Final Sur Total			3,872.93	

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Give	Xun
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	367.30	367.30	10.00	330.57	Replace	0	0	Not Give	Xun
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1	282.70	282.70	10.00	254.43	Replace	0	0	Not Give	Xun
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	Xun
Standard	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,401.70	1,401.70	25.00	1,051.28	Replace	1	1,051.28	Replace	bt-
Standard	Main			CHECK ASSY, REAR DOOR	1	199.40	199.40	25.00	149.55	Replace	0	0	Not Give	Xun
Standard	Main			HINGE ASSY, REAR DOOR , UPPER RH	1	107.00	107.00	25.00	80.25	Replace	0	0	Not Give	Xun
Standard	Main			HINGE ASSY, REAR DOOR , LOWER RH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	Xun
Standard	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , RH	1	996.60	996.60	10.00	896.94	Replace	0	0	Not Give	Xun
Standard	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1	223.50	223.50	25.00	167.63	Replace	0	0	Not Give	Xun
Standard	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	312.10	312.10	25.00	234.08	Replace	0	0	Not Give	Xun
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	943.10	943.10	25.00	707.33	Replace	1	707.33	Replace	but-
Standard	Main			PATCH, SIDE PANEL REAR END , RH & LH	1	37.70	37.70	25.00	28.28	Replace	0	0	Check	?
Standard	Main			LINER, REAR FENDER , RH	1	151.10	151.10	25.00	113.32	Replace	0	0	Check	?
Standard	Main			DUCT ASSY, QUARTER VENT , RH & LH	1	72.40	72.40	25.00	54.30	Replace	0	0	Check	?
Standard	Main			WHEEL, DISC	1	2,036.30	2,036.30	25.00	1,527.23	Replace	1	1,527.23	Replace	dit-
Standard	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check	?
Standard	Main			HUB & BEARING ASSY, RH & LH	1	722.10	722.10	25.00	541.58	Replace	0	0	Check)
Total Spare Part Cost									8,193.42	Surveyor Total		3,872.93		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									8,193.42	Final Sur Total		3,872.93		

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
8	Main	TO TRANSFER DOOR MECHANISM	120.00	60	
Total:			940.00	220.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,193.42	3,872.93
Total Labour Cost	1,690.00	1,000.00
Total Spray Painting	1,494.00	700.00
Other	940.00	220.00
Overall Total	12,317.42	5,792.93
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	5,792.93
Surveyor Approved Amount		5,792.93
No of Repair Days*	10	8
Remarks	-	PART BY PART / Before paint photo .FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 0740 6740/ EMAIL : taufikh@lkk.com.sg
Surveyor Name		Taufikh
Signature		
Survey Date	04 01/2023	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Taufikh 97495749
 WP 4/1/23
 P/P heavy before part
 taufikh@lkk.com.sg
 8days

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation			List Price(\$)	Dis(%)	Final Price(\$)	Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)				Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			MOULDING ASSY, BODY ROCKER PANEL, RH	1	649.10	649.10	25.00	486.83	Replace	1	0	Repair	
Total Spare Part Cost									8,193.42	Surveyor Total		3,872.93		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									8,193.42	Final Sur Total		3,872.93		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	1,690.00	1,000	
Total:			1,690.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY RIM	180.00	0	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
5	Main	TO RESPRAY RH REAR DOOR	378.00	200	
Total:			1,494.00	700.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	50	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
6	Main	TO REMOVE AND REFIX UNDERCARRIAGE	200.00	0	
Total:			940.00	220.00	