



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKX6703J MAZDA 3

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Headlamp RH <i>? Xnn</i>		2358.00	X
1	Grille top panel <i>de-</i>		352.00	
4	Grille top panel rivet@4*\$5 <i>m</i>		20.00	
4	Grille top panel clip@4*\$10 <i>m</i>		40.00	
1	Center grille <i>cr</i>		611.00	
2	Center grille inner side bracket RH/LH@2*\$17 <i>? Xnn</i>		34.00	X
1	Center grille logo badge <i>m</i>		47.00	
2	Center grille side lower chrome RH/LH@2*\$186 <i>cr</i>	3778	372.00	
1	Front bumper <i>de-</i>	206	1084.00	
2	Front bumper side retainer RH/LH@2*\$20 <i>Xnn</i>		40.00	X
2	Front bumper lower grille side garnish RH/LH@2*\$30 <i>Xnn</i>	3022.40	60.00	X
1	Front reinforcement <i>? Xnn</i>		594.00	X
1	Front bumper sponge <i>? Xnn</i>		98.00	X
1	Boot lid logo badge <i>m</i>		80.00	
1	Boot lid emblem "Mazda 3" <i>m</i>		57.00	
1	Boot lid emblem "Skyactiv Technology" <i>m</i>		67.00	
1	Rear bumper <i>de-</i>		1048.00	
2	Rear bumper side retainer RH/LH@2*\$38 <i>Xnn</i>		76.00	X
2	Rear bumper towing cover RH/LH@2*\$18 <i>Xnn</i>		36.00	X
2	Rear reverse sensor@2*\$204 <i>? Xnn</i>		408.00	<i>de 200? X</i>
1	Rear reinforcement <i>? Xnn</i>		565.00	X
1	Boot lid (Repair refer to labour)		0.00	
Part Items Total:			8047.00	
			-20% -1609.40	
			6437.60	
SPECIAL NETT ITEMS				
1	Front car plate <i>Xnn</i>		35.00	X
1	Front bumper clips <i>m</i>		35.00	<i>100</i>
1	Center grille clips <i>m</i>		30.00	
1	Rear bumper clips <i>m</i>		35.00	
SN Items Total:			135.00	
Total Parts			6572.60	



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKX6703J MAZDA 3

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	700
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	90.00	200.00 Xin
4	To perform anti-rust treatment on affected areas	60.00	nn
5	To remove, replace and focus headlamp	50.00	30
6	To remove and replace rear reverse sensor	100.00	40
Labour Total :		2300.00	
TOTAL (PARTS & LABOUR):		8872.60	


3022.40
160.00
1370.00
78.40
4570.80
208
3656.64
48-\$3,650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue
Ap 90010068
5 days
L/S
09/01/23 @ 1420
Reg after repair



Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Front reinforcement upper garnish <i>Cor ✓</i>		98.00	
			-20%	
			98.00	
			-19.60	
			78.40	
	<u>SPECIAL NETT ITEMS</u>			
			78.40	
	<u>LABOUR</u>			
		Total Parts	78.40	