

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 4771C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE (CONSISTENT)	DENTED	1,460.30	1,300.00
1	TAIL GATE LOGO(CONSISTENT)	NECESSARY	72.30	40.00
1	TAIL GATE EMBLEM 'FREED'(CONSISTENT)	NECESSARY	76.40	60.00
1	TAIL GATE INNER HOLDER (CONSISTENT)	NOT NECESSARY	80.00	-
1	TAIL GATE INNER TRIM (CONSISTENT)	CRACKED	350.00	350.00
1	TAIL GATE TOP LOCK (CONSISTENT)	CRACKED	232.10	232.10
2	TAIL GATE STOPPER @\$35.00(CONSISTENT)	CRACKED (1 PCS ONLY)	70.00	35.00
1	TAIL GATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	241.70	-
1	TAIL GATE OUTER OPENER (CONSISTENT)	NOT NECESSARY	233.60	-
1	TAIL GATE NUMBER PLATE (CONSISTENT)	NOT NECESSARY	90.00	-
1	TAIL GATE NUMBER PLATE GARNISH (CONSISTENT)	CRACKED	320.50	200.00
1	TAIL GATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	194.20	130.00
1	REAR BUMPER (CONSISTENT)	CUT	630.00	630.00
2	REAR BUMPER SIDE RETAINER @\$69.70(CONSISTENT)	NOT NECESSARY	139.40	-
1	REAR BUMPER TOW HOOK COVER (CONSISTENT)	NOT NECESSARY	55.90	-
2	TAILLAMP @\$410.00 (CONSISTENT)	BENT (1 PCS ONLY)	820.00	410.00
2	TAILLAMP PANEL @\$280.50(CONSISTENT)	TO REPAIR SEE LABOUR	561.00	-
2	REAR FENDER INNER TRIM @\$580.50(CONSISTENT)	CRACKED (1 PCS ONLY)	1,161.00	580.00
1	REAR END PANEL (OUTER)(CONSISTENT)	DENTED	520.00	520.00
1	REAR END PANEL (INNER)(CONSISTENT)	NOT NECESSARY	326.50	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	CRACKED	169.30	169.30
1	REAR FLOOR MAT (CONSISTENT)	NOT NECESSARY	1,550.90	-
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,830.00	-
	LESS 20% DISCOUNT		-2,237.02	-931.28
			8,948.08	3,725.12
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET TAIL GATE INNER BOARD CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00

Report Ref No. CC4/ASM23000122/Spa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET TAIL GATE NUMBER PLATE GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	TAIL GATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR END PANEL INSULATOR SEAL (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR FLOOR PANEL INSULATOR SEAL (SN) (CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR REVERSE SENSOR (SN) (CONSISTENT)	CRACKED	220.00	220.00
1	REAR REVERSE CAMERA (SN) (CONSISTENT)	NOT NECESSARY	380.00	-
			1,120.00	400.00
	<u>LABOUR</u>			
	PANEL BEATING ,WELDING ,CUTTING ,GRAZING ADJUST ,KNOCK STRAIGHTEN.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL AND REAR FLOOR PANEL .		1,400.00	650.00
	TO PUTTY ,SPRAY PAINT ,POLISH ,WAX.		1,400.00	650.00
	TO APPLY RUST PROOFING /UNDER COAT.	NOT NECESSARY	250.00	-
	WIRNING ,BULB CHECKING.		80.00	30.00
	REMOVE AND REFIX UPHOLSTERY ,CUSHION ,SEAT TO FACILITATE REPAIR .	NOT NECESSARY	250.00	-
	REMOVE AND REFIX TAILGATE WINDSCREEN .		120.00	80.00
	TO TRANSFER TAIL GATE MECHANISM .		80.00	30.00
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	100.00	-
	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING.		80.00	30.00
	REMOVE AND REFIX REAR REVERSE CAMERA AND DISTANCE SETTING.		80.00	30.00
			3,840.00	1,500.00
	GRAND TOTAL		13,908.08	5,625.12



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS	4,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM23000122/Spa3q2

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

Amont

HO LEONG CHUAN

Automotive Assessor