



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 5680T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RIGHT DOOR (CONSISTENT)	BENT	2,860.00	1,800.00
1	FRONT RIGHT DOOR HINGE (CONSISTENT)	TO REPAIR SEE LABOUR	262.00	-
1	FRONT RIGHT DOOR GARNISH (CONSISTENT)	CUT	496.00	446.40
1	FRONT RIGHT DOOR CHROME (CONSISTENT)	CUT	375.00	237.00
1	RIGHT REAR DOOR (CONSISTENT)	BENT	2,790.00	1,750.00
1	RIGHT REAR DOOR HINGE (CONSISTENT)	NOT NECESSARY	262.00	-
1	RIGHT REAR DOOR GARNISH (CONSISTENT)	CUT	496.00	446.40
1	RIGHT REAR DOOR CHROME (CONSISTENT)	CUT	375.00	237.00
1	RIGHT REAR DOOR HANDLE (CONSISTENT)	TO REPAIR SEE LABOUR	365.00	-
1	RIGHT REAR FUEL CAP (CONSISTENT)	TO REPAIR SEE LABOUR	221.00	-
1	RIGHT REAR FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	966.00	-
1	SIDE SKIRT GARNISH (CONSISTENT)	CUT	457.00	411.30
1	RIGHT REAR ALLOY RIMS (CONSISTENT)	CUT	1,550.00	920.00
	LESS 10% DISCOUNT		-1,147.50	-624.81
			10,327.50	5,623.29
<u>LABOUR</u>				
	TO FIX & DISMANTLE REMOVE DAMAGED FRONT & REAR RIGHT PORT AFFECTED DAMAGED PORTION.INCLUSIVE OF THE REPAIR OF FRONT RIGHT DOOR HINGE,RIGHT REAR DOOR HANDLE,RIGHT REAR FUEL CAP AND RIGHT REAR FENDER .		800.00	600.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS . (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING.		180.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS ,INCLUDING CHASSIS ALIGN.	NOT NECESSARY	600.00	-
	SPRAY PAINTING FOR FRONT & REAR RIGHT PORTIONS AFFECTED PARTS.		1,250.00	700.00
	REFOCUSING OF THE FRONT HEADLAMP. (NPA)	NOT NECESSARY	-	-
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE. (NPA)	NOT NECESSARY	-	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	3D WHEEL ALIGNMENT.		180.00	80.00
	TO APPLY WATERPROOFING SEALER ON END PANELS. (NPA)	NOT NECESSARY	-	-
			3,010.00	1,410.00
GRAND TOTAL			13,337.50	7,033.29
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,600.00

Report Ref No. CC4/ASM23000129/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.