

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA23000132/UVY3E2**Date:** 30/01/2023**REFERENCE**

Insured/Claimant:	Lim Swee Hock Alvin	Policy No:	MP305285	
Date of Loss:	03/01/2023	Nature of Claim:	OD	Claim No: MPC03938/SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB9840E	Engine No:	MR20861193B
Make & Model:	NISSAN X-TRAIL, 2.0 (A)	Chassis No:	JN1JANT32Z0001779
Reg. Date:	28/04/2016 (Man. Year: 2016)	Odometer:	78611 km
Colour:	Silver		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,429.15	7,762.55	1,666.60	17.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,170.00	1,030.00	46.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,629.15	8,932.55	2,696.60	23.19
Approved Total (Overridden) (S\$)		7,100.00		
- Excess (S\$)	625.00	625.00	0.00	0.00
(S\$)	11,004.15	6,475.00	4,529.15	41.16
+ GST 8.00/8.00% (S\$)	880.33	518.00	362.33	41.16
Nett Amount (S\$)	11,884.48	6,993.00	4,891.48	41.16

INSPECTION

Date of Assignment:	04/01/2023		
Date Inspected:	05/01/2023	Inspected At:	Tan Lim Motor Pte Ltd No.1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	M1-MPV	NISSAN X-TRAIL 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB9840E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Buckled	610.00 F	*610.00 F
2	4		*BONNET RUBBER (WCP)	Necessary	33.00 F	*33.00 F
3	1		*BONNET LOCK (WCP)	Twisted	72.00 F	*72.00 F
4	1		*RADIATOR (WCP)	Not Necessary	660.00 F	*- F
5	1		*RADIATOR GRILLE ASSY (WCP)	Cracked	330.00 F	*330.00 F
6	1		*RADIATOR GRILLE EMBLEM BADGE (WCP)	Not Necessary	66.00 F	*- F
7	1		*FRONT BUMPER (WCP)	Torn	440.00 F	*440.00 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	385.00 F	*385.00 F
9	1		*FRONT BUMPER SPONGE (WCP)	Torn	165.00 F	*165.00 F
10	2		*FRONT BUMPER SIDE RETAINERS (WCP)	Necessary	33.00 F	*33.00 F
11	1		*FRONT BUMPER LOWER AIR GRILLE (WCP)	Not Necessary	135.00 F	*- F
12	1		*FRONT BUMPER FASTEN CLIPS (8PCS)(WCP)	Necessary	2.50 F	*2.50 F
13	1		*FRONT SUPPORT PANEL - TOP (WCP)	Not Necessary	180.00 F	*- F
14	1		*FRONT SUPPORT CROSS RD (WCP)	Not Necessary	275.00 F	*- F
15	1		*AIR-CON CONDENSER (WCP)	Punctured	660.00 F	*660.00 F
16	1		*AUTO OIL COOLER (WCP)	Punctured	385.00 F	*385.00 F
17	2		*HEAD LAMP ASSY (WCP)	Holder Cracked	3,520.00 F	*3,520.00 F
18	1		*HORN HIGH TONE (WCP)	Not Necessary	95.00 F	*- F
19	1		*HORN LOW TONE (WCP)	Not Necessary	95.00 F	*- F
20	1		*FRONT AIR BAG SENSOR (WCP)	Bent / Damaged	385.00 F	*385.00 F
21	1		*FRONT LICENSE PLATE	Bent	50.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett.
					Sub Total (\$\$)	8,576.50 7,060.50
					+ Margin on L,N Items 10.00/10.00% (\$\$)	852.65 702.05
					Total Parts (\$\$)	9,429.15 7,762.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT	New	350.00	0.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
3	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	850.00	550.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	600.00
Gross Labour Cost (\$\$)			2,200.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >