

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23000134/TVY3E2**Date:** 03/04/2023REFERENCE

Insured/Claimant:	LIM CHEE HWA	Policy No:	0
Date of Loss:	30/12/2022	Nature of Claim:	OD Claim No: 202332004190

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBN8018A		
Make & Model:	LEXUS ES250, 2.5 4DR SEDAN EXECUTIVE (A)	Engine No:	A25A0217190
Reg. Date:	10/10/2018 (Man. Year: 2018)	Chassis No:	JTHB11B1302001552
Colour:	Black	Odometer:	0 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	S\$164,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,940.00	5,131.50	808.50	13.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	650.00	700.00	51.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,290.00	5,781.50	1,508.50	20.69
+ GST 8.00/8.00% (S\$)	583.20	462.52	120.68	20.69
Nett Amount (S\$)	7,873.20	6,244.02	1,629.18	20.69

INSPECTION

Date of Assignment:	04/01/2023	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	04/01/2023	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts:	143	LEXUS ES250 2.5 4DR SEDAN EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBN8018A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE (WCP)	Cut	750.00 F	*750.00 F
2	1		*FRONT GRILLE LOGO (WCP)	Not Necessary	420.00 F	*- F
3	1		*FRONT GRILLE CHROME TOP (WCP)	Cut	320.00 F	*320.00 F
4	1		*FRONT GRILLE CHROME LOWER (WCP)	Cut	350.00 F	*350.00 F
5	1		*FRONT HEADLAMP RH (WCP)	Cracked	1,950.00 F	*1,950.00 F
6	1		*FRONT HEADLAMP BRACKET RH (WCP)	Not Necessary	35.00 F	*- F
7	1		*FRONT BUMPER (WCP)	Deformed	580.00 F	*580.00 F
8	1		*FRONT BUMPER CHROME RH (WCP)	Cut	110.00 F	*110.00 F
9	1		*FRONT BUMPER SIDE GRILLE RH (WCP)	Deformed	70.00 F	*70.00 F
10	1		*FRONT BUMPER TOW COVER RH (WCP)	Cut	50.00 F	*50.00 F
11	1		*FRONT BUMPER SENSOR (WCP)	Not Working	200.00 F	*200.00 F
12	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	280.00 F	*- F
13	1		*FRONT BUMPER SPONGE (WCP)	Cracked	140.00 F	*140.00 F
14	10		*FRONT BUMPER RIVET (WCP)	Necessary	35.00 F	*35.00 F
Supplementary #1						
15	1		*FRONT NUMBER PLATE GARNISH (WCP)	Deformed	110.00 F	*110.00 F

F=Franchise part.

Sub Total (\$\$)	5,400.00	4,665.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	540.00	466.50
Total Parts (\$\$)	5,940.00	5,131.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR FRONT SUPPORT PANEL, FRONT CHASSIS MEMBER, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	500.00	250.00
2	TO SPRAY AFFECTED AREAS, BONNET, SUPPORT PANEK, FRONT BUMPER & AFFECTED AREAS	New	600.00	250.00
3	TO DIAGNOSTIC & PROGRAMMING WERE NECESSARY	New	250.00	150.00
Gross Labour Cost (S\$)			1,350.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >