

ASS. REC BY: T. J. J. J.REF: CSC1A152300013-1TVY

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. 202332004190Sum Insured: \_\_\_\_\_ Excess: 0

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: A164K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SBN 8018A - Yr Regn: 2018, OctType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota Lexus ES250 C.C. 2487Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: STHB 11B1302001552Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. \_\_\_\_\_ D.O.L. \_\_\_\_\_

Survey held at Mova BM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/3/23 Final fig \$5781.50 confirmed by email (red1508.50, 20%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 29/3/23-typist

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Wheel-end (\$

Rep. Format: Merimen

Lump Sum / L.B.J. \$5781.50

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	0	Date of Loss:	30/12/2022
Vehicle Reg. No.:	SBN8018A	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM CHEE HWA		
Make/Model:	LEXUS ES250, 2.5 4DR SEDAN EXECUTIVE (A)	Vehicle Reg. Date:	10/10/2018
Vehicle Colour:	Black		
Engine No:	A25A0217190	Chassis No:	JTHB11B1302001552
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	5,819.00
Miscellaneous Items	0.00
Labour	1,350.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$)</b>	<b>7,169.00</b>
<b>+ GST 8.00% (\$)</b>	<b>573.52</b>
<b>Nett Amount (\$)</b>	<b>7,742.52</b>

This claim is handled by: KEONG

**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2023)

Parts: 143 LEXUS ES250 2.5 4DR SEDAN EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SBN8018A/04/01/2023 18:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE	0.00	0.00	*750.00 F <i>cut</i>
2	1		*FRONT GRILLE LOGO	0.00	0.00	*420.00 F <i>X</i>
3	1		*FRONT GRILLE CHROME TOP	0.00	0.00	*320.00 F <i>?</i>
4	1		*FRONT GRILLE CHROME LOWER	0.00	0.00	*350.00 F <i>cut</i>
5	1		*FRONT HEADLAMP RH	0.00	0.00	*1,950.00 F <i>?</i>
6	1		*FRONT HEADLAMP BRACKET RH	0.00	0.00	*35.00 F <i>?</i>
7	1		*FRONT BUMPER	0.00	0.00	*580.00 F <i>de</i>
8	1		*FRONT BUMPER CHROME RH	0.00	0.00	*110.00 F <i>?</i>
9	1		*FRONT BUMPER SIDE GRILLE RH	0.00	0.00	*70.00 F <i>?</i>
10	1		*FRONT BUMPER TOW COVER RH	0.00	0.00	*50.00 F <i>cut</i>
11	1		*FRONT BUMPER SENSOR	0.00	0.00	*200.00 F <i>?</i>
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*280.00 F <i>?</i>
13	1		*FRONT BUMPER SPONGE	0.00	0.00	*140.00 F <i>?</i>
14	10		*FRONT BUMPER RIVET	0.00	0.00	*35.00 F <i>nu</i>
Sub Total (\$\$)						5,290.00
+ Margin on L,N Items 10.00% (\$\$)						529.00
Total Parts (\$\$)						5,819.00

F=Franchise part.

Mova Automotive Pte Ltd/SBN8018A/04/01/2023 18:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REPAIR FRONT SUPPORT PANEL, FRONT CHASSIS MEMBER, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	500.00 250
2	TO SPRAY AFFECTED AREAS, BONNET, SUPPORT PANEL, FRONT BUMPER & AFFECTED AREAS	New	600.00 250
3	TO DIAGNOSTIC & PROGRAMMING WERE NECESSARY	New	250.00 150?
<b>Gross Labour Cost (\$)</b>			<b>1,350.00</b>

Mova Automotive Pte Ltd/SBN8018A/04/01/2023 18:03. Not valid without Reference section.  
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749  
uk/25011aw  
Not Authorise Ex: tba  
P/P Resurvey before painting  
\* No 2nd-hand parts  
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: