

ASS. REC BY: TaujanREF: CSC/AIS2300013-1/Ty3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: A164K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBN 8018A - Yr Regn: 2018, OctType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Lexus ES250 C.C. 2487Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: _____ T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: STHB 11B1302001552Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.L. _____

Survey held at Mova BM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Workshop (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

Repair Format:

Lump Sum / L.B.J. / F

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	0	Date of Loss:	30/12/2022
Vehicle Reg. No.:	SBN8018A	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM CHEE HWA		
Make/Model:	LEXUS ES250, 2.5 4DR SEDAN EXECUTIVE (A)	Vehicle Reg. Date:	10/10/2018
Vehicle Colour:	Black		
Engine No:	A25A0217190	Chassis No:	JTHB11B1302001552
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	5,819.00
Miscellaneous Items	0.00
Labour	1,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	7,169.00
+ GST 8.00% (\$)	573.52
Nett Amount (\$)	7,742.52

This claim is handled by: KEONG

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2023)

Parts: 143 LEXUS ES250 2.5 4DR SEDAN EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SBN8018A/04/01/2023 18:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE	0.00	0.00	*750.00 F <i>cut</i>
2	1		*FRONT GRILLE LOGO	0.00	0.00	*420.00 F <i>X</i>
3	1		*FRONT GRILLE CHROME TOP	0.00	0.00	*320.00 F <i>?</i>
4	1		*FRONT GRILLE CHROME LOWER	0.00	0.00	*350.00 F <i>cut</i>
5	1		*FRONT HEADLAMP RH	0.00	0.00	*1,950.00 F <i>?</i>
6	1		*FRONT HEADLAMP BRACKET RH	0.00	0.00	*35.00 F <i>?</i>
7	1		*FRONT BUMPER	0.00	0.00	*580.00 F <i>de</i>
8	1		*FRONT BUMPER CHROME RH	0.00	0.00	*110.00 F <i>?</i>
9	1		*FRONT BUMPER SIDE GRILLE RH	0.00	0.00	*70.00 F <i>?</i>
10	1		*FRONT BUMPER TOW COVER RH	0.00	0.00	*50.00 F <i>cut</i>
11	1		*FRONT BUMPER SENSOR	0.00	0.00	*200.00 F <i>?</i>
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*280.00 F <i>?</i>
13	1		*FRONT BUMPER SPONGE	0.00	0.00	*140.00 F <i>?</i>
14	10		*FRONT BUMPER RIVET	0.00	0.00	*35.00 F <i>nu</i>
Sub Total (\$\$)						5,290.00
+ Margin on L,N Items 10.00% (\$\$)						529.00
Total Parts (\$\$)						5,819.00

F=Franchise part.

Mova Automotive Pte Ltd/SBN8018A/04/01/2023 18:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR FRONT SUPPORT PANEL, FRONT CHASSIS MEMBER, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	500.00 250
2	TO SPRAY AFFECTED AREAS, BONNET, SUPPORT PANEL, FRONT BUMPER & AFFECTED AREAS	New	600.00 250
3	TO DIAGNOSTIC & PROGRAMMING WERE NECESSARY	New	250.00 150?
Gross Labour Cost (S\$)			1,350.00

Mova Automotive Pte Ltd/SBN8018A/04/01/2023 18:03. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749
uk/25011aw
Not Authorise Ex: tba
P/P Resurvey before painting
* No 2nd-hand parts
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: