

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III23000135/KVY3E2**Date:** 28/02/2023REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 20/12/2022

Nature of Claim: OD

Claim No: MFL2022D0011880

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKW8150X**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZRY237591

Reg. Date: 18/11/2015 (Man. Year: 2015)

Chassis No: MR053REH104542717

Colour: Metallic Silver

Odometer: 57580 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$46,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Davanti 8 mm

Rear Left Side: Davanti 8 mm

Front Right Side: Davanti 8 mm

Rear Right Side: Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,878.87	4,487.25	1,391.62	23.67
Miscellaneous Items	111.00	111.00	0.00	0.00
Labour	2,280.00	1,620.00	660.00	28.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,269.87	6,218.25	2,051.62	24.81
Approved Total (Overridden) (S\$)		4,950.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	8,269.87	4,200.00	4,069.87	49.21
+ GST 8.00/8.00% (S\$)	661.59	336.00	325.59	49.21
Nett Amount (S\$)	8,931.46	4,536.00	4,395.46	49.21

INSPECTION

Date of Assignment: 05/01/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)

Date Inspected: 05/01/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)

205 Braddell Road
Singapore 579701

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW8150X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,498.40 FL	*1,248.10 FL
2	1		*FRONT BONNET INSULATOR	Serviceable	336.80 FL	*- FL
3	1		*FRONT BONNET LH HINGE	Repair	70.80 FL	*- FL
4	1		*FRONT BONNET RH HINGE	Distorted	70.80 FL	*70.80 FL
5	1		*FRONT BUMPER	Cracked	639.80 FL	*558.10 FL
6	1		*FRONT BUMPER RH RETAINER	Cracked	102.60 FL	*102.60 FL
7	1		*FRONT BUMPER UNDERCOVER	Serviceable	117.80 FL	*- FL
8	1		*FRONT RH FOGLAMP GARNISH	Serviceable	105.60 FL	*- FL
9	1		*FRONT RH FOGLAMP	Serviceable	394.10 FL	*- FL
10	1		*FRONT CHROME GRILLE	Cracked	204.20 FL	*204.20 FL
11	1		*FRONT RH FENDER	Bent	1,091.50 FL	*858.10 FL
12	1		*FRONT RH FENDER COWLING	Cracked	251.60 FL	*251.60 FL
13	1		*FRONT RH TOP SUPPORT PANEL	Bent	1,364.40 FL	*1,207.00 FL
14	1		*FRONT WIPER TANK	Dented	263.00 FL	*263.00 FL
15	1		*FRONT WIPER TANK NECK	Dented	70.40 FL	*70.40 FL
16	1		*FRONT REINFORCEMENT SPONGE	Serviceable	107.60 FL	*- FL
Supplementary #1						
17	1		*RH HEADLAMP	Broken	885.80 FL	*885.80 FL
18	1		*RH HEADLAMP CHROME MOULDING	Cracked	173.30 FL	*173.30 FL
19	1		*COOLANT SPARE TANK	Dented	90.00 FL	*90.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	7,838.50	5,983.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,959.63	1,495.75
Total Parts (\$)	5,878.87	4,487.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIP (NECESSARY)	50.00	50.00
2	1	FRONT FRNDER COWLING CLIP (NECESSARY)	50.00	50.00
3	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			111.00	111.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	1,200.00	700.00
2	To putty & respray on Front damage area.	New	1,000.00	900.00
3	To check wiring, focus headlamp.	New	80.00	20.00
Gross Labour Cost (\$\$)			2,280.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >