

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23000136/AQY3Q2**Date:** 20/06/2023**REFERENCE**

Insured/Claimant:	LIM KOK WAH	Policy No:	SPCM1000000313	
Date of Loss:	19/08/2022	Nature of Claim:	OD	Claim No: 202222006236

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GM7057P		
Make & Model:	NISSAN NAVARA, 2.5 D L D/CAB MT ABS D/AIRBAG TURBO (M)	Engine No:	YD25427249T
Reg. Date:	19/07/2012 (Man. Year: 2012)	Chassis No:	MNTVCUD40A0600006
Colour:	Grey	Odometer:	255182 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,995.55	4,382.26	8,613.29	66.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,040.00	1,890.00	3,150.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,035.55	6,272.26	11,763.29	65.22
Approved Total (Overridden) (S\$)		5,000.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	17,435.55	4,400.00	13,035.55	74.76

INSPECTION

Date of Assignment:	05/01/2023	
Date Inspected:	09/01/2023	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jun 2023)	
Parts:	N/A	NISSAN NAVARA 2.5 D L D/CAB MT ABS D/AIRBAG TURBO (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GM7057P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,076.20 FL	*1,076.20 FL
2	1		*REAR BUMPER CHROME SIDE	Not Necessary	208.60 FL	*- FL
3	1		*REAR BUMPER TOP STEP GARNISH	Deformed	298.60 FL	*298.60 FL
4	1		*REAR NUMBER PLATE GARNISH	Deformed	87.40 FL	*87.40 FL
5	1		*REAR NUMBER PLATE LAMP	Not Necessary	71.30 FL	*- FL
6	1		*REAR BUMPER BRACKET	Not Necessary	326.70 FL	*- FL
7	1		*TAIL LAMP LH	Cracked	564.30 FL	*355.00 FL
8	1		*TAIL LAMP PANEL LH	Not Necessary	198.40 FL	*- FL
9	1		*REAR SIDE PANEL LH	Distorted	2,265.50 FL	*1,950.00 FL
10	1		*TAIL GATE	Dented	798.50 FL	*798.50 FL
11	1		*TAIL GATE INNER COVER GARNISH	Not Necessary	3,946.20 FL	*- FL
12	1		*TAIL GATE EMBLEM NAVARA	Necessary	100.10 FL	*100.10 FL
13	1		*TAIL GATE LOGO	Necessary	125.60 FL	*125.60 FL
14	1		*TAILGATE CHAIN	Not Necessary	46.50 FL	*- FL
15	1		*TAIL GATE LOCK	Not Necessary	196.70 FL	*- FL
16	1		*TAIL GATE HINGE	Not Necessary	82.50 FL	*- FL
17	1		*TAIL GATE LOCK CATCH	Not Necessary	63.30 FL	*- FL
18	1		*REAR CARGO BED INNER GARNISH	Not Necessary	686.50 FL	*- FL
19	1		*REAR CARGO BED END PANEL	Not Necessary	1,296.60 FL	*- FL
20	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 FS	*- FS
22	1		*SET REAR BUMPER TOP STEP GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
23	1		*SET REAR NUMBER PLATE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
24	1		*SET TAIL LAMP CLIP	Necessary	50.00 FS	*10.00 FS
25	1		*TAIL LAMP PANEL LH SEALANT	Not Necessary	60.00 FS	*- FS
26	1		*REAR SIDE PANEL LH SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR SIDE PANEL RAILING LH	Not Necessary	450.00 FS	*- FS
28	1		*TAIL GATE SEALANT	Not Necessary	150.00 FS	*- FS
29	1		*SET TAIL GATE INNER COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
30	1		*TAIL GATE STICKER 3 PAX	Necessary	30.00 FS	*15.00 FS
31	1		*TAIL GATE STICKER 70 KM	Necessary	30.00 FS	*15.00 FS
32	1		*SET REAR CARGO BED INNER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
33	1		*REAR CARGO BED END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
34	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
35	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
					Sub Total (S\$)	14,239.50 4,861.40
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,243.95 479.14
					Total Parts (S\$)	12,995.55 4,382.26

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS STRAIGHTEN CHASSIS MEMBER	New	2,200.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	650.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK ON TAIL LAMP	New	120.00	30.00
5	REMOVE AND REFIX REAR RAILING	New	180.00	80.00
6	REMOVE AND REFIX REVERSE CAMERA	New	120.00	0.00
7	REMOVE AND REFIX REVERSE SENSOR	New	120.00	50.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
Gross Labour Cost (\$\$)			5,040.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >