



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR23000142/Kny3m4	
			Date: 12/01/2023	
			Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 5123R	Veh. Inspected	SJQ 7067D
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/12/22/2082	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	05/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA AIRWAVE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	GJ11304060	Colour	METALLIC GREY
	Odometer	243783 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/65 R15	DUNLOP	8 mm
	L/H Front Tyre	175/65 R15	DUNLOP	8 mm
	R/H Rear Tyre	175/65 R15	DUNLOP	8 mm
	L/H Rear Tyre	175/65 R15	DUNLOP	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
5. General Information				
	Accident Date	31/12/2022	Inspection Date	09/01/2023
	Survey held at	YAP MOTOR SERVICE PTE LTD BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	