

ASS. REC. BY:

REF:

AIG/23000149/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBT 32858 Yr Regn: 03, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Trace c.c. 2882Colour: Pink A/C: Insured / Std / NI / NASp. Reading: 181380 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTRHT02P500248594Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: MTY S/Rim / STD A/Rim orTyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 5 mmL/Bal. 7 mm L/Bal. 5 mmD.O.A. 13/12/22 D.O.I. 4/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls Rn body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/1, TTR, @ 3500 Cabul

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS. \$ _____

Fees: _____

Others: _____

TOTAL

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorised
11 Pp @ 3500h
Returning After Paint
4 days

REPAIR ESTIMATE GBJ3285Z

No.	Qty	List Items	
1	1	Front RH door	\$ <i>Pr</i> 1,410.35 ✓
2	1	Front RH door outer handle <i>139</i>	\$ <i>Cor</i> 185.60 ✓
3	1	Front RH door inner lock	\$ <i>R</i> 509.23 X
4	1	Front RH door rubber	\$ <i>R</i> 161.40 X
5	1 set	Front RH door inner trim board clips	\$ <i>nn</i> 60.00 X
6	1	RH door centre pillar	\$ <i>Pr</i> 466.95 ✓
7	1	RH sliding door <i>1545.10</i>	\$ <i>Pr</i> 1,916.10 ✓
8	1	RH sliding door outer handle	\$ <i>nn</i> 198.70 X
9	1	RH sliding door lower roller	\$ <i>nn</i> 299.10 X
10	1	RH sliding door lower roller bracket	\$ <i>R</i> 110.20 X
11	1	RH sliding door inner lock	\$ <i>R</i> 398.70 X
12	1	RH sliding door rubber	\$ <i>nn</i> 399.45 X
13	1 set	RH sliding door inner board clips	\$ <i>nn</i> 60.00 X
			\$ 6,175.78
			Less 25% \$ 1,543.95
			Total : \$ 4,631.84

Special Nett Items

14	1 set	RH door company name /contact no. sticker	\$ <i>nn</i> 450.00 <i>2001n</i>
----	-------	---	----------------------------------

Labour

1	Labour Charges for remove/refit and replace damage part:	\$ 1,100.00 <i>700</i>
2	To putty and spray Spray Paintings charges.	\$ 1,200.00 <i>600</i>
3	To check wirings.	\$ 40.00 <i>20</i>
4	To remove, refix front RH door fittings.	\$ 80.00 <i>60</i>
5	To remove, refit RH sliding door fittings.	\$ 80.00 <i>60</i>
6	To supply and apply anti rust treatment	\$ 80.00 ✓
		Total : \$ 2,580.00

Total Parts and Labour : \$ 7,661.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: