

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000151/UVP3E2**Date:** 22/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00101632206
Claimant Vehicle No :	GBJ2700Z	Insured Vehicle No :	YN8855C
Date of Loss:	04/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200060/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2700Z		
Make & Model:	RENAULT KANGOO, 1.5 D dCi (M)	Engine No:	K9KF647D092486
Reg. Date:	28/02/2019 (Man. Year: 2018)	Chassis No:	VF1FWT8H361486566
Colour:	Grey	Odometer:	92309 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,982.00	15,341.80	8,640.20	36.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,590.00	2,710.00	1,880.00	40.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,572.00	18,051.80	10,520.20	36.82
Approved Total (Overridden) (S\$)		14,200.00		
(S\$)	28,572.00	14,200.00	14,372.00	50.30
+ GST 8.00/8.00% (S\$)	2,285.76	1,136.00	1,149.76	50.30
Nett Amount (S\$)	30,857.76	15,336.00	15,521.76	50.30

INSPECTION

Date of Assignment:	04/01/2023	
Date Inspected:	05/01/2023 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Feb 2023)	
Parts:	N/A	RENAULT KANGOO 1.5 D dCi (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2700Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*AIRCON CONDENSER AIR GUIDE GARNISH	Torn	220.00 F	*220.00 FL
2	1	*FRONT BUMPER	Deformed / Torn	950.00 F	*950.00 FL
3	1	*FRONT BUMPER INNER AIR GUIDE	Cracked	280.00 F	*280.00 FL
4	1	*FRONT BUMPER REINFORCEMENT	Bent	600.00 F	*520.00 FL
5	2	*FRONT BUMPER SIDE BRACKET L/R	Not Necessary	280.00 F	*- FL
6	1	*FRONT GRILLE	Cracked	400.00 F	*400.00 FL
7	2	*FRONT GRILLE CENTER MOULDING L/R	Not Necessary	280.00 F	*- FL
8	1	*FRONT GRILLE INNER BRACKET	Not Necessary	390.00 F	*- FL
9	1	*FRONT GRILLE LOGO	Not Necessary	180.00 F	*- FL
10	1	*FRONT GRILLE LOWER MOULDING	Cut	260.00 F	*260.00 FL
11	2	*FRONT HEADLAMP L/R	Holder Cracked	1,160.00 F	*1,160.00 FL
12	1	*REAR BUMPER	Distorted	750.00 F	*750.00 FL
13	1	*REAR BUMPER LH REFLECTOR	Cracked	160.00 F	*160.00 FL
14	1	*REAR BUMPER REINFORCEMENT	Dented	420.00 F	*420.00 FL
15	1	*REAR BUMPER REINFORCEMENT FRAME GARNISH	Cracked	340.00 F	*340.00 FL
16	1	*REAR BUMPER REVERSE SENSOR (4PCS)	Shorted (2Pcs Only)	880.00 F	*330.00 FL
17	1	*SET REAR BUMPER REVERSE SENSOR HOLDER COVER	Not Necessary	150.00 F	*- FL
18	1	*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	420.00 F	*- FL
19	2	*REAR BUMPER SIDE RETAINER BRACKET L/R	Bent	300.00 F	*300.00 FL
20	1	*REAR BUMPER TOW HOOK COVER	Deformed	48.00 F	*48.00 FL
21	1	*REAR END PANEL	Dented / Bent	700.00 F	*700.00 FL
22	1	*REAR END PANEL INNER TOP GARNISH	Twisted	280.00 F	*280.00 FL
23	1	*REAR EXHAUST ALUMINIUM HEAT SHIELD	Bent	380.00 F	*380.00 FL
24	1	*REAR FLOOR PANEL	Repair	1,500.00 F	*- FL
25	1	*REAR LH GATE DOOR	Dented / Bent	1,900.00 F	*1,900.00 FL
26	1	*REAR LH GATE DOOR KANGOO EMBLEM	Necessary	130.00 F	*130.00 FL
27	1	*REAR LH GATE DOOR MAXI EMBLEM	Necessary	60.00 F	*60.00 FL
28	1	*REAR LH GATE DOOR CHECKER	Not Necessary	140.00 F	*- FL
29	1	*REAR LH GATE DOOR GLASS	Broken	580.00 F	*580.00 FL
30	1	*REAR LH GATE DOOR INNER TRIM BOARD	Torn	265.00 F	*265.00 FL
31	1	*REAR LH GATE DOOR LOWER HINGE	Not Necessary	155.00 F	*- FL
32	1	*REAR LH GATE DOOR LOWER LOCK	Twisted / Jammed	180.00 F	*180.00 FL
33	1	*REAR LH GATE DOOR MECHANISM LOCK	Jammed	380.00 F	*380.00 FL
34	1	*REAR LH GATE DOOR OUTER HANDLE	Damaged	250.00 F	*250.00 FL
35	1	*REAR LH GATE DOOR OUTER HANDLE INNER BASE HOLDER	Not Necessary	240.00 F	*- FL
36	1	*REAR LH GATE DOOR SPRING LINK	Not Necessary	110.00 F	*- FL
37	1	*REAR LH GATE DOOR WIPER ARM	Serviceable	170.00 F	*- FL
38	1	*REAR LH GATE DOOR WIPER ARM COVER	Serviceable	40.00 F	*- FL
39	1	*REAR LH GATE DOOR WIPER BLADE	Not Necessary	45.00 F	*- FL
40	1	*REAR LH GATE DOOR WIPER MOTOR	Jammed	590.00 F	*590.00 FL
41	1	*REAR NUMBER PLATE LAMP	Damaged	195.00 F	*195.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
42	1	*REAR RH GATE DOOR	Dented / Bent	1,790.00 F	*1,790.00 FL
43	1	*REAR RH GATE DOOR RENAULT EMBLEM	Necessary	149.00 F	*149.00 FL
44	1	*REAR RH GATE DOOR GLASS	Broken	450.00 F	*450.00 FL
45	1	*REAR RH GATE DOOR INNER TRIM BOARD	Not Necessary	195.00 F	*- FL
46	1	*REAR RH GATE DOOR LOWER LOCK	Jammed	220.00 F	*220.00 FL
47	1	*REAR RH GATE DOOR VERTICAL RUBBER SEAL	Twisted	235.00 F	*235.00 FL
48	1	*REAR SPARE TYRE CARRIER	Bent	690.00 F	*485.00 FL
49	1	*REAR SPARE TYRE CARRIER LOCK BRACKET	Bent	125.00 F	*125.00 FL
50	1	*REAR TAILGATE WEATHER STRIP	Twisted	330.00 F	*330.00 FL
51	1	*REAR TAILLAMP L/R	N/S Cracked	580.00 F	*290.00 FL
52	1	*REAR TAILLAMP LOWER GARNISH L/R	N/S Torn	520.00 F	*200.00 FL
53	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
54	1	*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
55	1	*FRONT NUMBER PLATE }	Bent	35.00 FS	*40.00 FS
56	1	*FRONT NUMBER PLATE HOLDER}		50.00 FS	*- FS
57	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
58	1	*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
59	1	*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
60	1	*REAR FLOOR PANEL INSULATOR PAD	Not Necessary	300.00 FS	*- FS
61	2	*REAR GATE DOOR GLASS SEAL L/R	Necessary	160.00 FS	*60.00 FS
62	2	*REAR GATE DOOR GLASS SEALANT L/R	Necessary	120.00 FS	*80.00 FS
63	2	*REAR GATE DOOR INNER TRIM BOARD CLIPS L/R	Not Necessary	80.00 FS	*- FS
64	1	*REAR LH GATE DOOR GLASS SOLAR FILM	Necessary	400.00 FS	*150.00 FS
65	1	*REAR NUMBER PLATE }	Scratched	35.00 FS	*40.00 FS
66	1	*REAR NUMBER PLATE HOLDER }		50.00 FS	*- FS
67	1	*REAR RH GATE DOOR 5PAX STICKER	Necessary	25.00 FS	*10.00 FS
68	1	*REAR RH GATE DOOR 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
69	1	*REAR RH GATE DOOR GLASS SOLAR FILM	Necessary	300.00 FS	*150.00 FS
70	2	*SET REAR TAILLAMP CLIPS L/R	Not Necessary	60.00 FS	*- FS
71	2	*SET REAR TAILLAMP LOWER GARNISH CLIPS L/R	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 23,982.00 16,972.00
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 1,630.20

Total Parts (\$\$) 23,982.00 15,341.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	250.00	0.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTNG HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	100.00	30.00
3	TO REMOVE, REINSTALL TAILGATE WINDSCREEN	New	240.00	240.00
4	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	50.00
5	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	1,000.00
6	TO REMOVE AND REINSTALL EXHAUST PIPE	New	120.00	0.00
7	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,000.00	1,200.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	90.00
9	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	120.00	100.00
Gross Labour Cost (\$\$)			4,590.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >