

SC Auto Industries (S) Pte Ltd (Co.Reg.No.19900107D)
 51 Senoko Road, #03-01
 Singapore 758133
 Tel: 67582222/65719972 Fax: 62576931 Email: sales@scauto.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMB1SNW00014232200	Date of Loss:	27/12/2022
Vehicle Reg. No.:	PC3099R	Driveable?	
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KIM TRANSPORT SOLUTION PTE LTD		
Driver:	TNG HUI TING		

Make/Model:	TOYOTA HIACE, 3.0 D DX (A)	Vehicle Reg. Date:	03/05/2015
Vehicle Colour:	METALLIC WHITE	Chassis No:	KDH2010157956
Engine No:	1KDH2010157956		
Odometer:	0 KM		

Paint Type:	METALLIC 2K
Total Loss?	NO
Est. Duration of Repair (day)	30 Days

Not Noted
1/1/23
Mercury After Paint
Ex 820001

Present Location: SC AUTO INDUSTRIES (S) PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	25,031.30
Miscellaneous Items	0.00
Labour	10,280.00
Paintwork Labour	0.00
Towing	150.00
Gross Total (S\$)	35,461.30
+ GST 8.00% (S\$)	2,836.90
Nett Amount (S\$)	38,298.20

This claim is handled by: RAYMOND TING SING WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source:

Parts: N/A

(Last Synchronised: 04 Jan 2023)

Labour: Repairer's

TOYOTA HIACE 3.0 D DX (A) (Model not available in database)

Print Code: SC Auto Industries (S) Pte Ltd/PC3099R/04/01/2023 18:37

(Price-denominated Standard List)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	Ry *785.60 F ✓
2	2		*FRONT HEADLIGHT LH & RH	0.00	0.00	mg Ro *2,880.40 F ✓
3	1		*BONNET LOCK	0.00	0.00	*268.20 F ?
4	1		*FRONT TOP GRILLE	0.00	0.00	cm *385.40 F ✓
5	1		*FRONT GRILLE LOWER	0.00	0.00	DT *885.40 F ✓
6	1		*FRONT GRILLE BASE	0.00	0.00	cm *823.10 F ✓
7	1		*FRONT WINDSCREEN	0.00	0.00	cm *1,240.10 F ✓
8	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	Ne *201.60 F ✓
9	1		*FRONT WINDSCREEN SEALANT	0.00	0.00	Ne *147.00 F ✓
10	1		*A/C CONDENSER	0.00	0.00	Ry *1,580.50 F ✓
11	1		*RADIATOR	0.00	0.00	*2,250.00 F ?
12	1		*SUPPORT PANEL ASSY	0.00	0.00	Ry *986.60 F ✓
13	2		*RETAINER LH & RH	0.00	0.00	Pt *328.50 F ✓
14	2		*HEADLAMP BRACKET LH & RH	0.00	0.00	*189.00 F ?
15	2		*FRONT BUMPER TOW COVER	0.00	0.00	ml *147.20 F ✓
16	1		*ENGINE LOWER COVER	0.00	0.00	Ro *680.40 F ✓
17	1		*COOLING FAN COVER	0.00	0.00	Ro *1,085.60 F ✓
18	2		*RADIATOR FLIP COVER LH & RH	0.00	0.00	Ro *571.20 F ✓
19	1		*A/C PIPE	0.00	0.00	*620.10 F ?
20	2		*COOLING FAN	0.00	0.00	Ro *1,102.80 F ✓
21	1		*COOLING FAN MOTOR	0.00	0.00	*1,797.60 F ?
22	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	Ry *956.60 F ✓
23	1		*HORN	0.00	0.00	*98.50 F ?
24	1		*AIR FILTER ASSEMBLY	0.00	0.00	Ro *1,550.90 F ✓
25	1		*STABILIZER BAR	0.00	0.00	*2,180.20 F ?
26	2		*STABILIZER LINK LH & RH	0.00	0.00	*971.20 F ?
27	4		*COOLANT	0.00	0.00	Ne *112.00 F ✓
28	1		*SIDE STEP COVER RH	0.00	0.00	Ro *205.60 F ✓

F=Franchise part.

Total Parts (\$\$)

25,031.30

SC Auto Industries (S) Pte Ltd/PC3099R/04/01/2023 18:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			2001
1	LABOUR TO REMOVE, REINSTALL AND CHECK STRUCTURE WIRE HARNESS.	New	650.00
2	LABOUR TO REMOVE AND REINSTALL FRONT WINDSCREEN	New	4001 600.00
3	LABOUR TO REFILL A/C GAS	New	1001 180.00
4	LABOUR TO REPLACE UNDERCARRIAGE COMPARTMENT. CHECK ACCORDING TO DAMAGE.	New	1,800.00 ?
5	LABOUR TO CARRY OUT WHEEL ALIGNMENT	New	601 250.00
6	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	New	300.00 ?
7	LABOUR TO RESPRAY SUPPORT PANEL ASSY, FRONT SIDE MEMBER LH & RH, CHASSIS FRAME, A-PILLAR LH & RH. 3x400	New	1200 2,000.00
8	LABOUR TO REMOVE, REPAIR, AND REINSTALL FRONT BUMPER, SUPPORT PANEL ASSY, FRONT SIDE MEMBER LH & RH, CHASSIS FRAME AND A-PILLAR LH & RH. CHECK ACCORDING TO DAMAGE	New	1400 4,500.00
Gross Labour Cost (\$\$)			10,280.00

SC Auto Industries (S) Pte Ltd/PC3099R/04/01/2023 18:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >