

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000158/AVP3Q2**Date:** 25/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00267022202
Claimant Vehicle No :	SME4548E	Insured Vehicle No :	SMQ8744R
Date of Loss:	04/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200092/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4548E	Engine No:	P520538708
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BN24A8J0243099
Reg. Date:	28/09/2018 (Man. Year: 2018)	Odometer:	57802 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,749.60	5,292.96	2,456.64	31.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,040.00	960.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,749.60	6,332.96	3,416.64	35.04
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	9,749.60	5,000.00	4,749.60	48.72
+ GST 8.00/8.00% (S\$)	779.97	400.00	379.97	48.72
Nett Amount (S\$)	10,529.57	5,400.00	5,129.57	48.72

INSPECTION

Date of Assignment:	05/01/2023		
Date Inspected:	02/05/2023	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2023)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME4548E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,080.10 FL	*1,080.10 FL
2	1		*FRONT BUMPER SIDE HOLDER -LH	Damaged	40.90 FL	*40.90 FL
3	1		*FRONT BUMPER FOG LAMP -LH	Not Necessary	320.50 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER -LH	Cut	85.50 FL	*85.50 FL
5	1		*FRONT BUMPER SIGNAL LAMP -LH	Not Necessary	327.20 FL	*- FL
6	1		*HEADLAMP -LH	Cut	3,778.20 FL	*3,778.20 FL
7	1		*FRONT FENDER -LH	Dented	581.60 FL	*581.60 FL
8	1		*FRONT FENDER INNER SHIELD -LH	Deformed	162.40 FL	*162.40 FL
9	1		*FRONT LOWER ARM	Not Necessary	541.30 FL	*- FL
10	1		*FRONT SHOCK ABSORBER	Not Necessary	420.40 FL	*- FL
11	1		*FRONT KNUCKLE ARM	Not Necessary	580.50 FL	*- FL
12	1		*FRONT WHEEL HUB C/W BEARING	Not Necessary	280.90 FL	*- FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*SET FRONT FENDER INNER SHIELD CLIPS -LH	Necessary	30.00 FS	*30.00 FS
15	1		*FRONT WHEEL RIM -LH	Cut	880.00 FS	*650.00 FS
16	1		*FRONT TYRE -LH	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,389.50	6,438.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,639.90	1,145.74
Total Parts (\$\$)	7,749.60	5,292.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING OUT FRONT LEFT PORTION & RENEW ABOVE PARTS	New	700.00	500.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	600.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	30.00
5	TO REMOVE FRONT UNDERCARRIAGE	New	350.00	0.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			2,000.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >