

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	R	Ref:	CS3/ASM23000165/Kvp3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	С	Date:	10/01/2023	
	ATTN: LOH CYNTH	AIA	C	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 8681G	Veh. Inspected		SLF 6770Y	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S3M04HFN	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		05/01/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CITY (A)	c.c		1497	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MRHGM6660HP000124	Colour		METALLIC BLACK	
	Odometer	46132 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/55 R16	YOKOHAMA		9 mm	
	L/H Front Tyre	185/55 R16	YOKOHAMA		9 mm	
	R/H Rear Tyre	185/55 R16	YOKOHAMA		9 mm	
	L/H Rear Tyre	185/55 R16	YOKOHAMA		9 mm	
4. Description of Damages						
	THE VEHICLE SUS	LE SUSTAINED DAMAGES AT THE N/S BODY.				
5.	General Information					
	Accident Date	31/12/2022	Inspect Date / Ti	ime	06/01/2023 (10:00 AM)	
	Survey held at	KUM CHEW MOTOR WORKSHOP				
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					

Report Ref No. CS3/ASM23000165/Kvp3e2

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

7 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser