

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000166/UVP3Q2**Date:** 01/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00017352200
Claimant Vehicle No :	GBE6219Y	Insured Vehicle No :	SLU5524U
Date of Loss:	03/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200106/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6219Y		
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M)	Engine No:	263A50007511389
Reg. Date:	01/02/2016 (Man. Year: 2015)	Chassis No:	ZFA26300006B55038
Colour:	Grey	Odometer:	157042 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,623.03	5,851.62	4,771.41	44.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,050.00	1,530.00	42.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,203.03	7,901.62	6,301.41	44.37
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	14,203.03	6,300.00	7,903.03	55.64
+ GST 8.00/8.00% (S\$)	1,136.24	504.00	632.24	55.64
Nett Amount (S\$)	15,339.27	6,804.00	8,535.27	55.64

INSPECTION

Date of Assignment:	05/01/2023	2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921 Repairer:N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
Date Inspected:	05/01/2023 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2023)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE6219Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	797.60 FL	*797.60 FL
2	1		*REAR BUMPER LOWER BRACKET	Bent	56.00 FL	*56.00 FL
3	2		*REAR BUMPER REFLECTOR L/R	Cracked	106.44 FL	*106.44 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	420.92 FL	*420.92 FL
5	1		*REAR BUMPER SIDE RETAINER L/R	N/S Cracked	70.20 FL	*35.10 FL
6	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	22.10 FL	*- FL
7	1		*REAR END PANEL (INNER)	Repair	680.00 FL	*- FL
8	1		*REAR END PANEL (OUTER)	Bent	700.00 FL	*700.00 FL
9	1		*REAR END PANEL INNER TOP GARNISH	Twisted	172.70 FL	*172.70 FL
10	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Not Necessary	390.00 FL	*- FL
11	1		*REAR LH TAILGATE	Badly Dented	1,820.10 FL	*1,820.10 FL
12	1		*REAR LH TAILGATE DOBLO EMBLEM	Necessary	88.14 FL	*88.14 FL
13	1		*REAR LH TAILGATE MAXI EMBLEM	Necessary	88.14 FL	*88.14 FL
14	1		*REAR LH TAILGATE CHECKER	Not Necessary	76.95 FL	*- FL
15	1		*REAR LH TAILGATE HINGE (LOWER)	Not Necessary	127.63 FL	*- FL
16	1		*REAR LH TAILGATE INNER TRIM BOARD	Deformed / Cracked	297.20 FL	*297.20 FL
17	1		*REAR LH TAILGATE LOCK STRIKER	Not Necessary	71.15 FL	*- FL
18	1		*REAR LH TAILGATE MECHANISM LOCK	Bent / Jammed	209.30 FL	*209.30 FL
19	1		*REAR LH TAILGATE OUTER GARNISH WITH HANDLE	Cracked	451.00 FL	*451.00 FL
20	1		*REAR RH TAILGATE	Repair	1,420.40 FL	*- FL
21	1		*REAR RH TAILGATE 90 MULTIJET EMBLEM	Necessary	44.17 FL	*44.17 FL
22	1		*REAR RH TAILGATE PROFESSIONAL EMBLEM	Necessary	88.10 FL	*88.10 FL
23	1		*REAR RH TAILGATE INNER TRIM BOARD	Not Necessary	232.10 FL	*- FL
24	1		*REAR RH TAILGATE MECHANISM LOCK (LOWER)	Not Necessary	240.37 FL	*- FL
25	1		*REAR TAILGATE WEATHER STRIP (VERTICAL)	Twisted	208.66 FL	*208.66 FL
26	1		*REAR SPARE TYRE CARRIAGE	Not Necessary	345.80 FL	*- FL
27	1		*REAR SPARE TYRE CARRIAGE BRACKET	Not Necessary	197.30 FL	*- FL
28	1		*REAR TAILLAMP L/R	N/S Cracked	925.34 FL	*462.67 FL
29	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
30	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
31	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*REAR LH TAILGATE 70KM STICKER	Necessary	25.00 FS	*10.00 FS
33	1		*REAR LH TAILGATE NUMBER PLATE	Not Necessary	35.00 FS	*- FS
34	1		*REAR LH TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
35	1		*REAR LH TAILGATE WINDSCREEN SEAL	Necessary	80.00 FS	*30.00 FS
36	1		*REAR LH TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*SET REAR RH TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*REAR RH TAILGATE WINDSCREEN SEAL	Not Necessary	80.00 FS	*- FS
39	1		*REAR RH TAILGATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*SET REAR TAILGATE ART WORK STICKER	Necessary	400.00 FS	*50.00 FS
41	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)11,657.816,456.24

- List Item Discount on L Items 10.00/10.00% (\$\$)1,034.78604.62

Total Parts (\$\$)10,623.035,851.62

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,AND REWIRE FOR PARKING SENSOR	New	60.00	20.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	300.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	950.00
5	TO REMOVE AND REINSTALL EXHAUST PIPE	New	100.00	0.00
6	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,500.00	880.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
Gross Labour Cost (\$\$)			3,580.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >